

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 685026-AFC
Project Name GOULBURN HOSPITAL
Project ID SYD191088.P003
Received Date Oct 29, 2019
Date Reported Oct 29, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID SYD191088.P003
Date Sampled Oct 28, 2019
Report 685026-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-Oc43779	CO865427	DP10	PEDESTRIAN ENTRY NEAR BH64	10:50	16:29	2.0	2.0	0/100	< 0.01
19-Oc43780	CO865556	DP20	VEHICLE ENTRY NEAR BH80	10:56	16:26	2.0	2.0	0/100	< 0.01
19-Oc43781	CO865404	DP19	FENCE ADJ NORTH BH44	11:00	16:24	2.0	2.0	0/100	< 0.01
19-Oc43782	CO865625	DP06	FENCE ADJ BH43	11:10	16:22	2.0	2.0	0/100	< 0.01
19-Oc43783	CO865430	DP15	FENCE ADJ BH20	11:15	16:21	2.0	2.0	0/100	< 0.01
19-Oc43784	CO865478	DP18	FENCE ADJ BH12	11:19	16:19	2.0	2.0	0/100	< 0.01
19-Oc43785	CO865462	DP04	FENCE ADJ BH53	11:27	16:17	2.0	2.0	0/100	< 0.01
19-Oc43786	CO865572	DP11	FENCE ADJ BH75	11:30	16:16	2.0	2.0	0/100	< 0.01

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-Oc43787	CO865469	DP05	INTERIOR LUNCH ROOM	11:35	16:35	2.0	2.0	17.5/100	0.01
19-Oc43788	CO865227	DP12	WALKWAY ADJ NORTH LUNCHROOM	12:30	16:42	2.0	2.0	0/100	< 0.01
19-Oc43789	CO901467	BLANK	BLANK	--	--	--	--	0/100	--

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Oct 29, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Oct 29, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: SYD191088.P003

Order No.:
Report #: 685026
Phone: 02 9809 0666
Fax:

Received: Oct 29, 2019 10:26 AM
Due: Oct 29, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	CO865427	Oct 28, 2019	4:29PM	Air	S19-Oc43779	X
2	CO865556	Oct 28, 2019	4:26PM	Air	S19-Oc43780	X
3	CO865404	Oct 28, 2019	4:24PM	Air	S19-Oc43781	X
4	CO865625	Oct 28, 2019	4:22PM	Air	S19-Oc43782	X
5	CO865430	Oct 28, 2019	4:21PM	Air	S19-Oc43783	X
6	CO865478	Oct 28, 2019	4:19PM	Air	S19-Oc43784	X
7	CO865462	Oct 28, 2019	4:17PM	Air	S19-Oc43785	X
8	CO865572	Oct 28, 2019	4:16PM	Air	S19-Oc43786	X
9	CO865469	Oct 28, 2019	4:35PM	Air	S19-Oc43787	X

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: SYD191088.P003

Order No.:
Report #: 685026
Phone: 02 9809 0666
Fax:

Received: Oct 29, 2019 10:26 AM
Due: Oct 29, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
10	CO865227	Oct 28, 2019	4:42PM	Air	S19-Oc43788	X
11	CO901467	Oct 28, 2019		Air	S19-Oc43789	X
Test Counts						11

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : Tim Kulmar, Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

██████████ Senior Analyst-Asbestos (NSW)

Authorised by:

██████████ Senior Analyst-Asbestos (NSW)

████████████████████

██████████

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Laboratory Report

Client: Eurofins | Mgt
Client address: 6 Monterey Road, DANDENONG SOUTH VIC 3175
Job number: 19_1868
Revision No. 0
Lab ID: 19_1868_01
Client ID: CO865469 (S19-Oc44406)
Date received: 30/10/19
Date analysed: 01/11/19
Date reported: 01/11/19
Analysis: Fibre characterisation by scanning electron microscopy (SEM) with elemental analysis by energy dispersive spectroscopy (EDS)

Executive summary

The sample was determined to **not contain** asbestos mineral fibre.

Sample preparation

The sampling was not conducted by Microanalysis Australia staff. The sample was supplied to Microanalysis Australia as a loaded 25 mm diameter MCE membrane. The membrane had been cut prior to receipt and only half was received.

A representative wedge-shaped sub-sample was cut from the filter membrane of about 1/6th of the total membrane size. The sub-sample was placed on top of a double-sided carbon tab before being coated with approximately 10 nm of carbon. Non-conducting samples require coating prior to SEM analysis to prevent charging whilst being analysed by the electron beam.

Analysis

The SEM/EDS analysis was conducted in accordance with ISO14966-2002 (modified for non-gold coated MCE membranes) and VDI3492-2004.

The sample was analysed using a Carl Zeiss EVO50 scanning electron microscope (SEM) fitted with an Oxford INCA X-Max energy dispersive spectrometer (EDS).

EDS is a semi-quantitative technique (at best) on well prepared, optically flat samples. Factors such as sample unevenness may adversely bias elemental concentration interpretation. EDS has a spatial resolution of ~5 µm meaning spectra from particles less than this size may contain elemental concentrations biased by their surroundings.

All images were acquired using backscatter electrons. Image brightness is proportional to average atomic number – the brighter the pixel, the higher the atomic number of the element.

Summary

Following NOHSC:3003 "The Membrane Filter Method" (2005), a fibre is countable if its diameter is < 3 µm and its length is > 5 µm and has an aspect ratio of greater than 3 to 1. Following the DMP document "Management of Asbestos in Mining Operations" page 3, referencing Section 9.33.3 of Mines, Safety and Inspection Regulations 1995, a fibre is countable if its diameter is < 1 µm and its length is > 5 µm. For the purposes of this analysis the NOHSC document definition has been used.

A total of **100** images/fields were examined. Each field was approximately 70 µm by 55 µm - a total area of 3.85 x 10³ mm².

In the **100** images/fields examined, a total of **less than 3** countable fibres were observed. **None of the observed countable fibres had an elemental composition indicative of asbestos mineral fibre.**

A selection of images/fields and associated elemental spectra are reported below. The fields are not representative of the 100 fields analysed. Asbestos mineral fibre or other inorganic mineral fibre has been preferentially shown.

Fibre #	Image/Field #	Diameter (µm)	Length (µm)	Aspect ratio	Major Elements	Minor Elements	Morphology	Assigned mineralogy
1	1/1	1.9	30.1	16 :1	O, C	-	Non-parallel sides	Organic
2	2/1	1.2	2.5	2 :1	O, Ti	-	Non-parallel sides	Rutile
3	3/1	0.5	2.6	5 :1	O, Si, Al	Fe, Mg, K	Non-parallel sides	Mica
4	4/1	1.2	5.5	5 :1	O, C	-	Non-parallel sides	Organic
5	5/1	0.8	3.1	4 :1	O, Ca, C	-	Non-parallel sides	Calcite



It should be noted that the higher resolution of the SEM may increase the number of fibres observed when compared with optical microscopy (as specified in the Membrane Filter Method). The results are representative only of the sample received.

Analyst: [REDACTED] B.Sc.(Multidisciplinary)



Reported: [REDACTED] B.Sc.(Multidisciplinary)

Authorised: [REDACTED], B.Sc.(Nanotechnology)



Sample: 19_1868_01 Type: Default ID: CO865469 (S19-Oc44406)	Project: 19_1868 Owner: lab Site: Site of Interest 1
---	--




Sample: 19_1868_01 Type: Default ID: CO865469 (S19-Oc44406)	Project: 19_1868 Owner: lab Site: Site of Interest 2
---	--



Sample: 19_1868_01 Type: Default ID: CO865469 (S19-Oc44406)	Project: 19_1868 Owner: lab Site: Site of Interest 3
---	--




Sample: 19_1868_01 Type: Default ID: CO865469 (S19-Oc44406)	Project: 19_1868 Owner: lab Site: Site of Interest 4
---	--



20µm

Electron Image 1





Be Confident We See More

This document may not be reproduced, except in full, without written approval



Sample: 19_1868_01 Type: Default ID: CO865469 (S19-Oc44406)	Project: 19_1868 Owner: lab Site: Site of Interest 5
---	--



Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 686151-V2-AFC
Project Name GOULBURN
Project ID 94054
Received Date Nov 04, 2019
Date Reported Nov 05, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN
Project ID 94054
Date Sampled Nov 01, 2019
Report 686151-V2-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No04350	BH53-SW	DP10	BOUNDARY FENCE	8:05	10:10	4.0	4.0	0/100	< 0.01
19-No04351	BH53-NW	DP19	BOUNDARY FENCE	8:06	10:11	4.0	4.0	0/100	< 0.01
19-No04352	BH53-N	DP11	PICKET	8:07	10:12	4.0	4.0	0/100	< 0.01
19-No04353	BH53-E	DP18	PICKET	8:09	10:40	4.0	4.0	0/100	< 0.01
19-No04354	BH53-S	DP20	PICKET	8:10	10:45	4.0	4.0	0/100	< 0.01
19-No04355	BH53-CLR	DP12	PICKET	8:50	11:10	4.0	4.0	0/100	< 0.01
19-No04356	BH56-SE	DP04	TEMP FENCE OUTSIDE SITE OFFICE	9:10	11:18	4.0	4.0	0/100	< 0.01
19-No04357	BH56-W	DP15	PICKET	9:09	11:16	4.0	4.0	0/100	< 0.01

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No04358	BH56-E	DP05	PICKET	9:10	11:18	4.0	4.0	0/100	< 0.01
19-No04359	BH56-CLR	DP18	PICKET	10:50	12:55	4.0	4.0	0/100	< 0.01
19-No04360	BH44-S	DP10	PICKET	10:13	15:50	4.0	4.0	0/100	< 0.01
19-No04361	BH44-E	DP19	BOUNDARY FENCE	10:14	15:29	4.0	4.0	0/100	< 0.01
19-No04362	BH44-N	DP11	BOUNDARY FENCE	10:15	12:39	4.0	4.0	0/100	< 0.01
19-No04363	BH44-CLR	DP20	STAR PICKET	11:25	13:50	4.0	4.0	0/100	< 0.01
19-No04364	BH-65-W	DP12	STAR PICKET	11:30	15:30	4.0	4.0	0/100	< 0.01
19-No04365	BH-65-E	DP05	VEHICLE ENTRY	11:35	15:59	4.0	4.0	0/100	< 0.01
19-No04366	BH-65-N	DP04	STAR PICKET	11:41	14:26	4.0	4.0	0/100	< 0.01
19-No04367	BH-65-S	DP11	FENCE TEMP	13:10	15:40	4.0	4.0	0/100	< 0.01
19-No04368	BH-65-SW	DP15	FENCE TEMP	13:11	15:36	4.0	4.0	0/100	< 0.01

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 04, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 04, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN
Project ID: 94054

Order No.:
Report #: 686151
Phone: 02 9809 0666
Fax:

Received: Nov 4, 2019 3:22 PM
Due: Nov 4, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	BH53-SW	Nov 01, 2019	10:10AM	Air	S19-No04350	X
2	BH53-NW	Nov 01, 2019	10:11AM	Air	S19-No04351	X
3	BH53-N	Nov 01, 2019	10:12AM	Air	S19-No04352	X
4	BH53-E	Nov 01, 2019	10:40AM	Air	S19-No04353	X
5	BH53-S	Nov 01, 2019	10:45AM	Air	S19-No04354	X
6	BH53-CLR	Nov 01, 2019	11:10AM	Air	S19-No04355	X
7	BH56-SE	Nov 01, 2019	11:18AM	Air	S19-No04356	X
8	BH56-W	Nov 01, 2019	11:16AM	Air	S19-No04357	X
9	BH56-E	Nov 01, 2019	11:18AM	Air	S19-No04358	X

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN
Project ID: 94054

Order No.:
Report #: 686151
Phone: 02 9809 0666
Fax:

Received: Nov 4, 2019 3:22 PM
Due: Nov 4, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
10	BH56-CLR	Nov 01, 2019	12:55PM	Air	S19-No04359	X
11	BH44-S	Nov 01, 2019	3:50PM	Air	S19-No04360	X
12	BH44-E	Nov 01, 2019	3:29PM	Air	S19-No04361	X
13	BH44-N	Nov 01, 2019	12:39PM	Air	S19-No04362	X
14	BH44-CLR	Nov 01, 2019	1:50PM	Air	S19-No04363	X
15	BH-65-W	Nov 01, 2019	1:30PM	Air	S19-No04364	X
16	BH-65-E	Nov 01, 2019	3:59PM	Air	S19-No04365	X
17	BH-65-N	Nov 01, 2019	2:26PM	Air	S19-No04366	X
18	BH-65-S	Nov 01, 2019	3:40PM	Air	S19-No04367	X
19	BH-65-SW	Nov 01, 2019	3:36PM	Air	S19-No04368	X
Test Counts						19

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement [REDACTED], Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

This report has been amended (V2) to amend sample names.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised by:

[REDACTED] Senior Analyst-Asbestos (NSW)

[REDACTED]

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 686304-AFC
Project Name GOULBURN HOSPITAL
Project ID 94054
Received Date Nov 05, 2019
Date Reported Nov 05, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID 94054
Date Sampled Oct 31, 2019
Report 686304-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No05635	INTERIOR EAST END LUNCHROOM	DP18	INTERIOR EAST END LUNCHROOM	11:06	14:00	4.0	4.0	18/100	0.01
19-No05636	INTERIOR WEST END LUNCHROOM	DP19	INTERIOR WEST END LUNCHROOM	11:07	14:01	4.0	4.0	22/100	0.01
19-No05637	FIELD BLANK	BLANK	BLANK	--	--	--	--	0/100	--

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 05, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 05, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
 West Ryde
 NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054

Order No.:
Report #: 686304
Phone: 02 9809 0666
Fax:

Received: Nov 5, 2019 12:40 PM
Due: Nov 5, 2019
Priority: Same day
Contact Name:

Eurofins Analytical Services Manager :

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	INTERIOR EAST END LUNCHROOM	Oct 31, 2019	2:00PM	Air	S19-No05635	X
2	INTERIOR WEST END LUNCHROOM	Oct 31, 2019	2:01PM	Air	S19-No05636	X
3	FIELD BLANK	Oct 31, 2019		Air	S19-No05637	X
Test Counts						3

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED] Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within Holding Time	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised by:

[REDACTED] Senior Analyst-Asbestos (NSW)

[REDACTED]

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
 The results of the tests, calibrations and/or
 measurements included in this document are traceable
 to Australian/national standards.

Attention: [REDACTED]
Report 686305-AFC
Project Name GOULBURN HOSPITAL
Project ID 94054
Received Date Nov 05, 2019
Date Reported Nov 05, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID 94054
Date Sampled Oct 31, 2019
Report 686305-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No05639	NE CORNER LUNCHROOM	DP11	NE CNR LUNCHROOM	9:38	14:02	2.0	2.0	1/100	< 0.01
19-No05640	NW CORNER LUNCHROOM	DP05	NW CNR LUNCHROOM	9:39	14:03	2.0	2.0	0/100	< 0.01
19-No05641	SE CORNER LUNCHROOM	DP04	SE CNR LUNCHROOM	9:40	14:04	2.0	2.0	2/100	< 0.01
19-No05642	SW CORNER LUNCHROOM	DP15	SW CNR LUNCHROOM	9:41	14:05	2.0	2.0	0/100	< 0.01
19-No05643	FIELD BLANK	BLANK	BLANK	--	--	--	--	0/100	--

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 05, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 05, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054

Order No.:
Report #: 686305
Phone: 02 9809 0666
Fax:

Received: Nov 5, 2019 12:40 PM
Due: Nov 5, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	NE CORNER LUNCHROOM	Oct 31, 2019	2:02PM	Air	S19-No05639	X
2	NW CORNER LUNCHROOM	Oct 31, 2019	2:03PM	Air	S19-No05640	X
3	SE CORNER LUNCHROOM	Oct 31, 2019	2:04PM	Air	S19-No05641	X
4	SW CORNER LUNCHROOM	Oct 31, 2019	2:05PM	Air	S19-No05642	X
5	FIELD BLANK	Oct 31, 2019		Air	S19-No05643	X
Test Counts						5

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED], Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised by:

[REDACTED] Senior Analyst-Asbestos (NSW)



General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 686443-AFC
Project Name GOULBURN
Project ID 94054
Received Date Nov 06, 2019
Date Reported Nov 06, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN
Project ID 94054
Date Sampled Nov 05, 2019
Report 686443-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No06671	BH67-N	DP11	LONG WALL	7:02	13:48	2.0	2.0	0/100	< 0.01
19-No06672	BH67-SW	DP05	FENCE	6:55	13:49	2.0	2.0	0/100	< 0.01
19-No06673	BH67-SE	DP20	FENCE	7:03	13:50	2.0	2.0	0/100	< 0.01
19-No06674	BH67-W	DP04	TRUCK TURN	7:05	13:52	2.0	2.0	0/100	< 0.01
19-No06675	BH67-CLR	DP10	EXCAVATOR	11:40	14:05	4.0	4.0	0/100	< 0.01
19-No06676	FIELD BLANK	BLANK	BLANK	--	--	--	--	0/100	--

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 06, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 06, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN
Project ID: 94054

Order No.:
Report #: 686443
Phone: 02 9809 0666
Fax:

Received: Nov 6, 2019 10:01 AM
Due: Nov 6, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	BH67-N	Nov 05, 2019	1:48PM	Air	S19-No06671	X
2	BH67-SW	Nov 05, 2019	1:49PM	Air	S19-No06672	X
3	BH67-SE	Nov 05, 2019	1:50PM	Air	S19-No06673	X
4	BH67-W	Nov 05, 2019	1:52PM	Air	S19-No06674	X
5	BH67-CLR	Nov 05, 2019	2:05PM	Air	S19-No06675	X
6	FIELD BLANK	Nov 05, 2019		Air	S19-No06676	X
Test Counts						6

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : Tim Kulmar, Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

██████████ Senior Analyst-Asbestos (NSW)

Authorised by:

██████████ Senior Analyst-Asbestos (NSW)

████████████████████
██████████

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
 The results of the tests, calibrations and/or
 measurements included in this document are traceable
 to Australian/national standards.

Attention: [REDACTED]
Report 686445-AFC
Project Name GOULBURN
Project ID 94054
Received Date Nov 06, 2019
Date Reported Nov 06, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN
Project ID 94054
Date Sampled Nov 04, 2019
Report 686445-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No06682	BH65-SE	DP20	GH02	7:19	16:01	2.0	2.0	4/100	< 0.01
19-No06683	BH65-NE	DP12	GH01	7:18	16:07	2.0	2.0	0/100	< 0.01
19-No06684	BH65/66-S	DP11	P66	7:21	16:02	2.0	2.0	4/100	< 0.01
19-No06685	BH66-S	DP18	GH03	7:22	16:03	2.0	2.0	0/100	< 0.01
19-No06686	BH67-SW	DP05	P50	7:14	16:04	2.0	2.0	2.5/100	< 0.01
19-No06687	BH67-N	DP19	2	7:16	16:06	2.0	2.0	1/100	< 0.01
19-No06688	BH65/66-CLR	DP04	GH06	8:14	12:40	4.0	4.0	0/100	< 0.01
19-No06689	BH56-E	DP15	GH07	11:51	16:05	4.0	4.0	0/100	< 0.01

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No06690	BH66-CLR	DP10	GHO5	14:00	16:15	4.0	4.0	4.5/100	< 0.01

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 06, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 06, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN
Project ID: 94054

Order No.:
Report #: 686445
Phone: 02 9809 0666
Fax:

Received: Nov 6, 2019 10:01 AM
Due: Nov 6, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						CANCELLED	Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271							
Sydney Laboratory - NATA Site # 18217						X	X
Brisbane Laboratory - NATA Site # 20794							
Perth Laboratory - NATA Site # 23736							
External Laboratory							
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID		
1	BH65-SE	Nov 04, 2019	4:01PM	Air	S19-No06682		X
2	BH65-NE	Nov 04, 2019	4:07PM	Air	S19-No06683		X
3	BH65/66-S	Nov 04, 2019	4:02PM	Air	S19-No06684		X
4	BH66-S	Nov 04, 2019	4:03PM	Air	S19-No06685		X
5	BH67-SW	Nov 04, 2019	4:04PM	Air	S19-No06686		X
6	BH67-N	Nov 04, 2019	4:06PM	Air	S19-No06687		X
7	BH65/66-CLR	Nov 04, 2019	12:40PM	Air	S19-No06688		X
8	BH56-E	Nov 04, 2019	4:05PM	Air	S19-No06689		X
9	BH66-CLR	Nov 04, 2019	4:15PM	Air	S19-No06690		X

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN
Project ID: 94054

Order No.:
Report #: 686445
Phone: 02 9809 0666
Fax:

Received: Nov 6, 2019 10:01 AM
Due: Nov 6, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						CANCELLED	Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271							
Sydney Laboratory - NATA Site # 18217						X	X
Brisbane Laboratory - NATA Site # 20794							
Perth Laboratory - NATA Site # 23736							
10	FIELD BLANK	Nov 04, 2019		Air	S19-No06691	X	
Test Counts						1	9

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED], Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within Holding Time	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised by:

[REDACTED] Senior Analyst-Asbestos (NSW)

[REDACTED]

[REDACTED]

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 687268-AFC
Project Name GOULBURN HOSPITAL
Project ID 94054
Received Date Nov 11, 2019
Date Reported Nov 11, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID 94054
Date Sampled Nov 08, 2019
Report 687268-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No13064	BH71-EAST	DP05	BH71-EAST	9:26	14:45	2.0	2.0	0/100	< 0.01
19-No13065	BH71-NORTH	DP11	BH71-NORTH	9:26	14:43	2.0	2.0	0/100	< 0.01
19-No13066	BH71-SOUTH	DP04	BH71-SOUTH	9:22	14:40	2.0	2.0	0/100	< 0.01
19-No13067	BH71-WEST	DP20	BH71-WEST	9:24	14:41	2.0	2.0	0/100	< 0.01
19-No13068	FIELD BLANK	BLANK	BLANK	--	--	--	--	0/100	--
19-No13069	BH44-EAST	DP12	BH44-EAST	7:32	14:31	2.0	2.0	4.5/100	< 0.01
19-No13070	BH44-CLR	DP10	BH44-CLR	8:58	14:38	2.0	2.0	0/100	< 0.01
19-No13071	BH44-NORTH	DP18	BH44-NORTH	7:30	14:30	2.0	2.0	1/100	< 0.01

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No13072	BH44-SOUTH	DP15	BH44-SOUTH	7:34	14:33	2.0	2.0	4/100	< 0.01
19-No13073	BH44-WEST	DP19	BH44-WEST	7:36	14:35	2.0	2.0	0/100	< 0.01

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 11, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 11, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
 West Ryde
 NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054

Order No.:
Report #: 687268
Phone: 02 9809 0666
Fax:

Received: Nov 11, 2019 9:00 AM
Due: Nov 11, 2019
Priority: Same day
Contact Name:

Eurofins Analytical Services Manager :

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	BH71-EAST	Nov 08, 2019	2:45PM	Air	S19-No13064	X
2	BH71-NORTH	Nov 08, 2019	2:43PM	Air	S19-No13065	X
3	BH71-SOUTH	Nov 08, 2019	2:40PM	Air	S19-No13066	X
4	BH71-WEST	Nov 08, 2019	2:41PM	Air	S19-No13067	X
5	FIELD BLANK	Nov 08, 2019		Air	S19-No13068	X
6	BH44-EAST	Nov 08, 2019	2:31PM	Air	S19-No13069	X
7	BH44-CLR	Nov 08, 2019	2:38PM	Air	S19-No13070	X
8	BH44-NORTH	Nov 08, 2019	2:30PM	Air	S19-No13071	X
9	BH44-SOUTH	Nov 08, 2019	2:33PM	Air	S19-No13072	X

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
 West Ryde
 NSW 2114
Project Name: GOULBURN HOSPITAL
Project ID: 94054

Order No.:
Report #: 687268
Phone: 02 9809 0666
Fax:

Received: Nov 11, 2019 9:00 AM
Due: Nov 11, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
10	BH44-WEST	Nov 08, 2019	2:35PM	Air	S19-No13073	X
Test Counts						10

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED], Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments


Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised by:

[REDACTED] Senior Analyst-Asbestos (NSW)



General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
 The results of the tests, calibrations and/or
 measurements included in this document are traceable
 to Australian/national standards.

Attention: [REDACTED]
Report 687579-AFC
Project Name GOULBURN HOSPITAL
Project ID 94054
Received Date Nov 12, 2019
Date Reported Nov 12, 2019

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID 94054
Date Sampled Nov 11, 2019
Report 687579-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No15964	CO865931	DP19	BH47 SOUTH	7:18	11:10	3.0	3.0	0/100	< 0.01
19-No15965	CO866103	DP12	BH47 WEST	7:20	11:12	3.0	3.0	0/100	< 0.01
19-No15966	CO866038	DP18	BH47 EAST	7:22	11:14	3.0	3.0	0/100	< 0.01
19-No15967	CO866075	DP15	BH47 NORTH	7:24	11:16	3.0	3.0	1/100	< 0.01
19-No15968	CO865929	DP20	BH71 SOUTH	8:23	11:18	3.0	3.0	0/100	< 0.01
19-No15969	CO865959	DP10	BH71 WEST	8:25	11:20	3.0	3.0	0/100	< 0.01
19-No15970	CO865897	DP11	BH71 BASE	8:41	11:23	3.0	3.0	0/100	< 0.01
19-No15971	CO865908	DP05	65/66 SOUTH	8:32	11:26	3.0	3.0	0/100	< 0.01

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
19-No15972	CO866044	DP04	65/66 EAST	8:34	11:29	3.0	3.0	0/100	< 0.01
19-No15973	CO866141	BLANK	BLANK	--	--	--	--	0/100	--

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Nov 12, 2019	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Nov 12, 2019	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
 West Ryde
 NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054

Order No.:
Report #: 687579
Phone: 02 9809 0666
Fax:

Received: Nov 12, 2019 2:25 PM
Due: Nov 12, 2019
Priority: Same day
Contact Name:

Eurofins Analytical Services Manager :

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
External Laboratory						
No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	CO865931	Nov 11, 2019	11:10AM	Air	S19-No15964	X
2	CO866103	Nov 11, 2019	11:12AM	Air	S19-No15965	X
3	CO866038	Nov 11, 2019	11:14AM	Air	S19-No15966	X
4	CO866075	Nov 11, 2019	11:16AM	Air	S19-No15967	X
5	CO865929	Nov 11, 2019	11:18AM	Air	S19-No15968	X
6	CO865959	Nov 11, 2019	11:20AM	Air	S19-No15969	X
7	CO865897	Nov 11, 2019	11:23AM	Air	S19-No15970	X
8	CO865908	Nov 11, 2019	11:26AM	Air	S19-No15971	X
9	CO866044	Nov 11, 2019	11:29AM	Air	S19-No15972	X

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054

Order No.:
Report #: 687579
Phone: 02 9809 0666
Fax:

Received: Nov 12, 2019 2:25 PM
Due: Nov 12, 2019
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail						Asbestos (concentration of fibres in air)
Melbourne Laboratory - NATA Site # 1254 & 14271						
Sydney Laboratory - NATA Site # 18217						X
Brisbane Laboratory - NATA Site # 20794						
Perth Laboratory - NATA Site # 23736						
10	CO866141	Nov 11, 2019		Air	S19-No15973	X
Test Counts						10

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED] Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins | mgt and therefore volume measurements contained in this report are traceable back to Eurofins | mgt. Eurofins | mgt are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	Yes
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised by:

[REDACTED] Senior Analyst-Asbestos (NSW)

[REDACTED]

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.





Accredited for compliance
with ISO 9001
Testing

ail en re ec ma

COGRD MTRG R T R R T

December

Attention

Compan

ma

Ti ar

Douglas Partners Pty Ltd

Ti ar do glaspartners.co.a



WORLD RECOGNISED
ACCREDITATION

Accredited for compliance
with ISO 17025
Testing

Report Reference

CAM

Site address

Goldbom Hospital Redevelopment Faithfull Street Goldbom

Sampling Date

December

Period sampling

–

Site

Air monitoring during excavation works in onshore fill

Site Sampling Location

Site Sampling Location Chambers Dickson Place Dickson ACT

Accreditation number

Site number

Introduction Background monitoring for airborne asbestos fibres where undertaken by Safe Work and Environments Pty Ltd (SWE) is used to assess the concentration of background airborne asbestos fibres during site works.

Method

Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method – Air Polye Measure Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method – Asbestos Air Fibre Mount and Count.

Results

Site	Control Point	Result	Control Point Result
CAM	Site boundary fence adjacent Community Health centre		
CAM	Site boundary fence adjacent Faithfull St vehicle entry		
CAM	Site boundary fence adjacent firefighting water tanks		
CAM	Track route to containment cell west edge of fleet carpark		
CAM	ATF fence on east wall of containment cell		
CAM	ATF fence on south wall of containment cell		
CAM	Site boundary fence west of containment cell		
CAM	Exterior site entrance north wall		
CAM	Site boundary fence adjacent Goldsmith St north of containment cell		
CAM	Field Control (Blank)		

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

CAM Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environments Ltd

Site Sampling Location Chambers Dickson Place Dickson ACT

Phone

Email



CGRDMTRG R TRRT

December




Concn All reportable air fibre levels reported on within this report are below the lowest detectable level of fibres/L of air

named and reported



Analyst



Approved Issuer of Report

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

CGRDMTRG Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environment Ltd

Site Suite 1000 Dickson Chambers Dickson Place Dickson ACT

Phone 02 9292 9292

Email info@safe.com.au

Name _____
Site _____
Phone _____
E-mail _____

and Environment Ltd
Discussions Chambers
Discussions Place
Discussions ACT
re: ecma

COGRIND MORTAR GOR TOTT ROTT

December 2020

Attention
Comedian
ma

Tiatar
Douglas Partners Pty Ltd
Tiaatar dooglaspartners.co.a



Accredited for compliance
with ISO 17025
Testing

Report Reference CAA
Site Address Goldbom Hospital Redevelopment Faithful Street Goldbom
Sampling Date December 2020
Period of Sampling 08:00 – 16:00
Issue Air monitoring during excavation works in onshore fill
Site Location Site Section Division Chambers Division Place Division ACT

Accreditation number **Site number**

Introduction Background monitoring for airborne asbestos fibres were undertaken by Safe Work and Environments Pty Ltd (SWE) is used to assess the concentration of background airborne asbestos fibres during site works.

Method Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method – Air Polye Measurment Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method – Asbestos Air Fibre Mount and Count.

Results

Location	Controlled Area	Result	Controlled Area Result
CAAS	Site boundary fence adjacent Community Health centre		
CAAS	Site boundary fence adjacent Faithful St vehicle entry		
CAAS	Site boundary fence adjacent firefighting water tanks		Refect
CAAS	Track route to containment cell west edge of fleet carpark		
CAAS	ATF fence on east wall of containment cell		
CAAS	ATF fence on south wall of containment cell		
CAAS	Site boundary fence west of containment cell		
CAAS	Exterior site anchorage north wall		
CAAS	Site boundary fence adjacent Goldsmith St north of containment cell		
CAAS	Field Control (Blank)		

Sample rejected due to initial/final air flow rate outside of allowed flow variation of 10%

Period of Sampling defined by the on/off of the first air monitoring sample to the off/on of the last air monitoring sample

CAA Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environments Ltd

Site Section Division Chambers Division Place Division ACT

Phone 02 9999 9999

Email en@e.com.au

CONFIDENTIAL MTD REPORT

December

Conclusion All reportable air fibre levels reported on within this report are below the lowest detectable level of fibres/L of air

named and reported

Redacted Name

Analyst and Approved Issuer of Report

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

CONFIDENTIAL AAM Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environment Ltd

Site Suite 1000 Dickson Chambers Dickson Place Dickson ACT

Phone 02 9292 9292

Email enquiries@ecma.com.au

COGRD MTRG R T R R T

December

Attention

Compan

ma

Ti ar

Doglas Partners Pty Ltd

Ti ar doglaspartners.co.a



Accredited for compliance
with ISO/IEC 17020
Testing

Report Reference

CAM

Site Address

Goldbom Hospital Redevelopment Faithful Street Goldbom

Sampling Date

December

Period Sampling

–

Scope

Air monitoring during excavation works in onhoon fill

Site Location

Site Section Division Chambers Division Place Division ACT

Accreditation number

Site number

Introduction Background monitoring for airborne asbestos fibres were undertaken by Safe Work and Environments Pty Ltd (SWE) is used to assess the concentration of background airborne asbestos fibres during site works.

Method

Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method – Air Polye Measurement Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method – Asbestos Air Fibre Mount and Count.

Results

Location	Control Point Description	Result	Control Point Result
CAM	Site boundary fence west of containment cell		Refect
CAM	Site boundary fence adjacent Goldsmith St north of containment cell		
CAM	Site boundary fence adjacent Community Health Centre north of fleet car park area		
CAM	Site boundary fence adjacent Faithful St site vehicle entry east of fleet car park area		
CAM	Site boundary fence adjacent Water tanks south of fleet car park area		
CAM	Star picket west of fleet car park area adjacent road		
CAM	ATF fence east side of containment cell		
CAM	ATF fence on south side of containment cell		
CAM	Western site boundary fence adjacent concrete emergency exit stairwell east of road		
CAM	Field Control (Blank)		NA

Sample relected due to initial final air flow rate outside of allowed flow variation of

Period of Sampling defined by the on/off of the first air monitoring sample to the off/on of the last air monitoring sample

CAM Asbestos Air Monitoring Report


Page 1 of 1

Safe Work and Environments Ltd

Site Section Division Chambers Division Place Division ACT


Phone

Email



Cncnn All reportable air fibre levels reported on within this report are below the lowest detectable level of fibres/L of air

David Langton
Analyst



Page 1 of 1

Site S Dic son Cha bers Dic son Place Dic son ACT
Phone
 ail en re ec ma

BACKGROUND MONITORING FOR ASBESTOS FIBRES RESULTS

13 December 2019

Attention: [REDACTED]
Company: Douglas Partners Pty Ltd
Email: [REDACTED]



Accredited for compliance
with ISO/IEC 17025 -
Testing

SWE Report Reference: C108603-AAM1.v1-121219
Site Address: Goulburn Hospital Redevelopment, Faithfull Street, Goulburn.
Sampling Date: 12 December 2019
Period of Sampling¹: 06:28 – 16:33
Scope: Air monitoring during excavation works in unknown fill.
SWE Laboratory: Suite S1, 25 Dickson Chambers, Dickson Place, Dickson ACT 2602

Accreditation number: 17092 **Site number:** 23867

- 1. Introduction:** Background monitoring for airborne asbestos fibres where undertaken by Safe Work and Environments Pty Ltd (SWE) is used to assess the concentration of background airborne asbestos fibres during site works.
- 2. Methods:** Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 2 – Air Volume Measurement. Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 1 – Asbestos Air Fibre Mount and Count.

3. Results:

SWE REF.	LOCATION OF SAMPLE	FIBRES/ FIELDS	CONCENTRATION (FIBRES/mL)
C108603/S547/121219	Site boundary fence, north-west of containment cell.	1.0/100	<0.01
C108603/S515/121219	Site boundary fence, north-east of containment cell.	1.0/100	<0.01
C108603/S590/121219	Site boundary fence, adj. Community Health Centre BLD, north of excavation.	0.0/100	<0.01
C108603/S575/121219	Site boundary fence, adj. Faithfull St site vehicle entry, east of excavation.	0.0/100	<0.01
C108603/S421/121219	Site boundary fence, adj. water tanks, south of excavation.	0.0/100	<0.01
C108603/S393/121219	Star picket, adj. site office and truck transport route.	2.0/100	<0.01
C108603/S571/121219	ATF fence on south-east corner of containment cell.	0.0/100	<0.01
C108603/S588/121219	Star picket adj. decontamination area and south-west of containment cell	0.0/100	<0.01
C108603/S755/121219	Site boundary fence, west of truck transport route.	1.0/100	<0.01
C108603/S566/121219	Field Control (Blank).	0.0/100	N/A

¹ Period of Sampling defined by the on-time of the first air monitoring sample to the off-time of the last air monitoring sample.

BACKGROUND MONITORING FOR ASBESTOS FIBRES RESULTS

13 December 2019



4. Conclusion: All reportable air fibre levels reported on within this report are below the lowest detectable level of 0.01 fibres/mL of air.

[Redacted]

[Redacted]

[Redacted]

Analyst

[Redacted]

[Redacted]

Approved Issuer of Report

^{*} Period of Sampling defined by the on-time of the first air monitoring sample to the off-time of the last air monitoring sample.

Accredited for compliance
with ISO 11000
Testing

□ □ C □ G R □ □ □ D M □ □ T □ R □ □ G □ □ R □ □ □ □ T □ □ □ □ R □ □ R □ □ □ T □

□□ an□ary □□□□

Content: Title
 Company: Douglas Partners Pty Ltd
 Manager: Title: douglaspartners.co.au

☐ ☐ Report Reference ☐ Community AAM ☐

☐ Address ☐ Goibm Hospital Rede ☐ elop ☐ ent ☐ Faithful Street ☐

☐ Ending Date ☐ January ☐

☐ Period ☐ Ending ☐ – ☐

☐ c ☐ e ☐ Air ☐ monitoring d ☐ ring exca ☐ tion ☐ or s along northern e ☐ ban ☐ ent ☐
☐ ☐ ☐ a ☐ r ☐ t ☐ Site S ☐ ☐ ☐ Dic ☐ son Cha ☐ bers ☐ Dic ☐ son Place ☐ Dic ☐ son ACT ☐ ☐

ccred fat n n m er

Background Monitoring for airborne asbestos fibres here undertaken by Safe Air and Ironbents Pty Ltd (SAL) is used to assess the concentration of background airborne asbestos fibres.

Method Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method 4 – Air Polye Measurement Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method 4 – Asbestos Air Fibre Moisture and Count

Ret

□□ □ R□□□	□□C□T□□ □ □ □M□□□	□□R□□□ □□□D□	C□□C□□TR□T□□ □□□R□□m□□
C□□□□□□\$□□□□□□□□□□	□astern peri□ eter fence (Faithf□□ St)□ad□fire hydrant□east of proposed fleet carpar□□	□□□□□□□	□□□□□
C□□□□□□\$□□□□□□□□□□	□orthern peri□ eter fence□ad□Co□ □ □nity Health Centre□	□□□□□□□	□□□□□
C□□□□□□\$□□□□□□□□□□	□orth□estern peri□ eter fence□ad□Co□ □ □nity Health Centre□load o□ area and decon □nit□	□□□□□□□	□□□□□
C□□□□□□□ □□□□□□□□□□	So□thern peri□ eter fence□east of site office and so□th of □or□area□ad□fire fighting □ater tan□□	□□□□□□□	□□□□□
C□□□□□□\$□□□□□□□□□□	□ eastern delineation fence□west of □or□area□	□□□□□□□	□□□□□
C□□□□□□\$□□□□□□□□□□	□orth□estern delineation fence□ad□load o□ area□	□□□□□□□	□□□□□
C□□□□□□\$□□□□□□□□□□	Field Control (Blan□)□	□□□□□□□	□A

□□C□nc□□□□□□□□ All reportable air fibre levels reported on □□ithin this report are below the lowest detectable level of □□□□ fibres□□ L of air□

named and reported

Paul Lynch

David Langton
Analyst

J. Barnes

Approved Issuer of Report

□Period of Sa□pling defined by the on□□e of the first air □onitoring sa□ple to the off□□e of the last air □onitoring sa□ple□

C AAM Asbestos Air Monitoring Report

Page 1 of 1

are and environment that

Site Section Division Division Place Division ACT

[illegible]

ail en re e c m a

CONTROL MONITORING REPORT

December

Attention
Companion
ma

Ti
Douglas Partners Pty Ltd
Ti
do



Accredited for compliance
with ISO 17020
Testing

Report Reference C
Site Address G
Sampling Date December
Period Sampling –
Issue Air monitoring during excavation works in fill known to contain asbestos
Site Location Site Section Chambers Section Place Section ACT

Accreditation number
Site number

Introduction Control monitoring for airborne asbestos fibres here undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal related work

Method Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method – Air Polysaccharide Measurement Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method – Asbestos Air Fibre Mount and Count

Results

Location	Control Monitoring	Result	Control Measure
Control Point 1	Southwest corner of Community Health Services BLD attached to boundary fence		
Control Point 2	Southern end of Community Health Services BLD adjacent to excavation area attached to boundary fence		
Control Point 3	Southeast corner of site eastern side of excavation area attached to boundary fence		
Control Point 4	Southeast corner of site southwest corner of excavation area attached to delineation fencing		
Control Point 5	Attached to delineation fencing between site office and remediation area		
Control Point 6	Attached to delineation fencing adjacent to site office		
Control Point 7	Attached to delineation fencing at decontamination unit		
Control Point 8	Eastern side of containment cell attached to boundary fence from northwest corner of site		
Control Point 9	Northern side of containment cell attached to boundary fence		
Control Point 10	Field Control (Blank)		

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

CAM Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environments Ltd
Site Section Chambers Section Place Section ACT
Phone
Email

CONTROL MONITORING REPORT

December



Concentration All reportable air fibre levels reported on within this report are below the lowest detectable level of fibres/L of air

named and reported



David Langton
Analyst



David Langton
Approved Issuer of Report

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

Control Monitoring Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environment Ltd

Site Suite 1000 Dickson Chambers Dickson Place Dickson ACT

Phone 02 9291 1111

Email info@swandenv.com.au

CONTROL MONITORING REPORT

December

Client: Ti
Company: Douglas Partners Pty Ltd
Manager: Ti



Accredited for compliance
with ISO 18646
Testing

Report Reference: C
Site Address: Gordon Hospital Redevelopment Faithful Street Gordon
Sampling Date: December
Period Sampling: –
Issue: Air monitoring during excavation works in fill known to contain asbestos
Site Status: Site Specific Decision Chambers Decision Place Decision ACT

Accreditation number: Site number:

Introduction: Control monitoring for airborne asbestos fibres here undertaken by Safe Work and Environments Pty Ltd (SWE) is used to verify the effectiveness of control measures implemented to prevent fibre release as a result of asbestos removal related work

Method: Airborne asbestos fibre monitoring was carried out in accordance with the Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003 (2005)] and SWE's In-House Method – Air Bole Measurment Analysis of collected filter membrane samples was performed in accordance with NOHSC:3003 (2005) and SWE's In-House Method – Asbestos Air Fibre Mount and Count

Results

Location	Control Measure	Result	Control Measure
Control Measure	Eastern side of containment cell attached to boundary fence from SW corner of site		
Control Measure	Northern side of containment cell attached to northern boundary fence id day along		
Control Measure	Southwest corner of Community Health Services building attached to boundary fence		
Control Measure	South of Community Health Services building attached to boundary fence adjacent to excavation area		Reflected
Control Measure	Southeast corner of site attached to boundary fence on east side of excavation area		Reflected
Control Measure	Attached to delineation fencing between site office and remediation area		
Control Measure	Attached to delineation fencing and gate to asbestos work area adjacent to site office		
Control Measure	Attached to delineation fencing at decontamination unit		
Control Measure	Attached to delineation fencing adjacent to SW corner of Community Health Services building		
Control Measure	Field Control (Blank)		NA

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

Control Measure Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environments Ltd
Site Specific Decision Chambers Decision Place Decision ACT
Phone
Email: info@ecma



CONTROL MONITORING OF RISK OF ASBESTOS EXPOSURE

11 December 2020

Sample rejected due to pump battery failure on screen in

Sample rejected due to initial/final flow rate outside of allowed flow variation of 10%

Conclusion All reportable air fibre levels reported on within this report are below the lowest detectable level of 0.01 fibres/mL of air

Analysed and reported by



David Langston
Analyst



Jared Jarne
Approved Issuer of Report

Attached Site Plan with Air Monitoring Locations

Period of Sampling defined by the on-site of the first air monitoring sample to the off-site of the last air monitoring sample

Controlled Area Monitoring Asbestos Air Monitoring Report

Page 1 of 1

Safe Work and Environment Ltd

Site Services Division Chambers Division Place Division ACT 2600

Phone 02 9292 9292

Email enquiries@ecma.com.au



TERMINAL TREATMENT OF ASBESTOS CLEARANCE CERTIFICATE

Canary

Attention
Companion Douglas Partners
Manager Peter Storey do@glaspartners.co.uk
Client Reference – Goiborn Hospital Redevelopment

Project
Date
Effect Removal
Site Address
Company
Canary
Affect Services
Goiborn Hospital Redevelopment Faithful Street Goiborn SA

Dear Peter

Re: Clearance Certificate for Effect Removal and Containment of

Introduction

Safe Work and Environment Pty Ltd (SWE) was engaged by Douglas Partners to undertake an Asbestos Clearance Inspection following the removal of insitu soil containing nonfriable asbestos cement sheeting from part of old containment pit. The works were conducted to facilitate redevelopment works of Goiborn Hospital. Licensed Asbestos Assessor David Langston (LAA) carried out an inspection of the removal area following completion of the removal works at site on the Canary.

The scope of work included the following:

- Visual Inspection of the subject areas following the asbestos removal works as per the scope of removal.
- Preparation of an Asbestos Clearance Report outlining the site data, conclusions and recommendations (if necessary).

Removal

Soil and asbestos containing material (ACM) was removed from part of old containment pit. An approximate area measuring was excavated from old containment pit down to a depth between below ground level. The depth of excavation was undertaken to approximately below below earthworks depth. Once the excavation was complete a geotextile barrier layer was installed on the base and walls of the excavation and approximately of clean fill placed over the barrier layer. An approximate location of the removal area is included in Figure 1.

CLR Asbestos Clearance Certificate

Safe Work and Environment Ltd
Site Maors Bay Road
Concord NSW
Ph Fax
Email enquiries@se.co.uk

Canberra Office
PO Box Dickson ACT
Ph

Inspection Details

Areas inspected within the asbestos removal area by the assessor included:

- Visible and accessible surface soils within old containment pit

No suspect asbestos material or debris associated with the scope of removal was identified by the assessor during the inspection. Photos of the removal area are included in *Appendix 1*

Control air monitoring was undertaken during removal. All airborne fibre concentrations were below the reporting limit of 0.001 fibres/mL of air.

It is the opinion of the assessor the removal works undertaken by Affectix Services is of appropriate industry standard and in accordance with adopted Code of Practice: *How to Safely Remove Asbestos* (2001).

Conclusion & Recommendations

Based on the data presented in this report it is the opinion of Safe Work & Environments Pty Ltd that:

- Soils impacted with asbestos cement sheeting have been removed from the surface of the old containment pit.
- The assessor found no visible asbestos debris from asbestos removal work in the area or in the vicinity of the area where the work was carried out.
- It is the opinion of the assessor the inspected area is safe in regards to asbestos to be re-occupied by unprotected persons (providing surface soils are not disturbed).
- Soils within the old containment pit are likely to contain asbestos material beneath the surface layer. Soil disturbance within the area of the old containment pit should be undertaken with appropriate asbestos work controls in place (in accordance with the site's asbestos management plan).
- If any additional asbestos materials are identified within the site at a later date, work must cease for the asbestos materials to be removed. All asbestos removal of work should be carried out in accordance with the NSW Safe Work Australia 2001 Code of Practice: *How to Safely Remove Asbestos* or as directed by the task specific asbestos safety work procedures.

Should you have any queries regarding this certificate please do not hesitate to contact the undersigned for further information or assistance.

Yours faithfully,

Enironmental Consultant
 Michael Langston, Secretary
 Affectix and Enironment Pty Ltd
 PO Box 1111 Dickson ACT 2600
 P 02 6261 1111
www.affectix.com.au

Figure 1 Asbestos Removal Work Area
 Appendix 1 Site Photographs

Canberra CLR 001 Asbestos Clearance Certificate

Affectix and Enironment Pty Ltd
 Site 1111 Maors Bay Road
 Concord NSW 2137
 Ph 02 6261 1111 Fax 02 6261 1111
www.affectix.com.au

Canberra Office
 PO Box 1111 Dickson ACT 2600
 Ph 02 6261 1111

Figure 1 Asbestos Removal Work Area

C[] [] [] [] [] CLR [] [] [] [] [] Asbestos Clearance Certificate

a e r and n r nment t td
 Site Maors Bay Road
 Concord S
 Ph Fax
 ail Enries se.co a

Canberra
PO Box
Ph

Appendix Site Photographs

Canberra CLR Asbestos Clearance Certificate

Safe Work and Environment Australia
Site 10000 Maors Bay Road
Concord NSW 1592
Ph (02) 9339 1000 Fax (02) 9339 1001
Email enquiries@seco.a

Canberra Office
PO Box 1000 Dickson ACT 2600
Ph (02) 9339 1000





Photograph prior to containment cell excavation. Note black plastic on site office and entry was restricted.



Photograph Post excavation and geotextile barrier evident on pit walls.

Completed CLR Asbestos Clearance Certificate

Safe Work and Environment Ltd
Site 1000s Maors Bay Road
Concord NSW
Ph 02 9438 1000 Fax 02 9438 1001
Email enquiries@seco.au

Canberra Office
PO Box 1000 Dickson ACT
Ph 02 9438 1000



Photograph 1 Post excavation and geotextile liner evident on pit walls. Not varying depth of excavation to accommodate future site works.



Photograph 2 Post excavation and geotextile liner evident and use of clean fill.

Canberra CLR Asbestos Clearance Certificate

Safe Work and Environment Australia
Site 1000 Maors Bay Road
Concord NSW 1592
Phone 02 9555 1111 Fax 02 9555 1112
Email enquiries@seco.a.gov.au

Canberra Office
PO Box 1000 Dickson ACT 2600
Phone 02 9555 1111

ASBESTOS CLEARANCE CERTIFICATE

10 January 2019

Attention: [REDACTED]
Company: Douglas Partners
Email: Peter.Storey@douglaspartners.co.uk

Project: [REDACTED] Clearance
Date: 10 January 2019
Effect: Removal
Site: [REDACTED] Gloucester Hospital Redevelopment, Faithful Street, Gloucester, GL1 2RH

Dear Peter,

Re: Clearance Certificate for Decontamination of Decontamination Unit at Gloucester Hospital Redevelopment, Faithful Street, Gloucester

Introduction

Safe Work and Environments Pty Ltd (SWE) was engaged by Douglas Partners to undertake a visual Asbestos Clearance Inspection following decontamination works on a Decontamination Unit (Decontamination Unit A). Licensed Asbestos Assessor David Langston (LAA000000) carried out an inspection of the works area following decontamination works at [REDACTED] on the 10 January 2019.

The scope of work included the following:

- Visual Inspection of the subject areas following the asbestos removal works as per the scope of removal.
- Preparation of an Asbestos Clearance Report outlining the site data, conclusions and recommendations (if necessary).

Photographs of the Decontamination Unit area included in Appendix A.

Clearance Removal

The removal of asbestos debris from Decontamination Unit Decontamination Unit A.

Inspection Details

Areas inspected by the assessor included the visible and accessible internal and external wall and floor surfaces of the decontamination unit to suspect asbestos material or debris as identified by the assessor during the inspection.

It must be noted that the clearance inspection did not include inaccessible surfaces and materials such as drainage pipes and filters.

CLR000000 Asbestos Clearance Certificate Decontamination Unit Decontamination Unit A

Safe Work and Environments Ltd
Site: [REDACTED] Maors Bay Road
Concord NSW 1592
Phone: [REDACTED] Fax: [REDACTED]
Email: [REDACTED]

Canberra Office
PO Box [REDACTED] Dickson ACT 2600
Phone: [REDACTED]

It is the opinion of the assessor the removal/decontamination works undertaken by Affectiive Services is of appropriate industry standard and in accordance with adopted Code of Practice: *How to Safely Remove Asbestos* (2001)

Conclusion & Recommendation

Based on the data presented in this report it is the opinion of Safe Work & Environments Pty Ltd that

- The assessor found no visible asbestos materials within Decontamination Unit Decontamination Area
- The visible and accessible surfaces of the Unit Decontamination Area have been successfully decontaminated of asbestos material
- The scope of this clearance report does not cover inaccessible surfaces and materials such as drainage pipes and filters
- Based on the results of the inspection it is the opinion of the assessor the inspected area is safe in regard to the asbestos risk and may be used by unprotected persons
- The decontamination unit internal negative air filter was left in place and is to be replaced by the hire company
All asbestos removal works should be carried out in accordance with the Safe Work Australia 2001 Code of Practice: *How to Safely Remove Asbestos* or as directed by the task specific asbestos safe work procedures

Should you have any queries regarding this certificate please do not hesitate to contact the undersigned for further information or assistance

Yours faithfully

Daniel Langston

Environmental Consultant

Daniel Langston Services Pty Ltd

Safe Work & Environments Pty Ltd

PO Box 1111 Dickson ACT 2600

Ph 02 9399 9999

02 9399 9999

Attachment 1 – Photographs

02 9399 9999 CLR 0000 Asbestos Clearance Certificate Decontamination Unit Decontamination Area

Safe Work & Environments Pty Ltd 0000 0000 0000 0000

Site 0000 Maors Bay Road

Concord NSW 2138

Ph 02 9399 9999 Fax 02 9399 9999

02 9399 9999 02 9399 9999

Canberra Office

PO Box 1111 Dickson ACT 2600

Ph 02 9399 9999

Attachment 1 – Photograph



Photograph 1 Deconta ination unit



Photograph 2 Interior of Deconta ination unit

Company CLR 1234 Asbestos Clearance Certificate Deconta ination unit C123456789A

Safe Work and Environment Ltd 1234 5678901234

Site 12345 Maors Bay Road

Concord NSW 1234

Phone 1234 5678 Fax 1234 5678

Email enquiries@seco.au

Canberra Office

PO Box 123456 Dickson ACT 1234

Phone 1234 5678



Photograph 1 Interior of Decontamination Unit

Completed CLR Asbestos Clearance Certificate Decontamination Unit C-1000 A

Safe Work and Environment Ltd
 Site 10000 Maors Bay Road
 Concord NSW 1592
 Phone 02 9600 1000 Fax 02 9600 1000
 Email enquiries@seco.au

Canberra Office
 PO Box 1000 Dickson ACT 2600
 Phone 02 9600 1000

□□ □an□ary □□□□

Project C
Date January
Website Affective Services
Address Goiborn Hospital Redevelopment Faithful Street Goiborn S

Dear Peter☐

R00C000000 – 0000a0Clearance Certificate 00r 00e0t00 Rem00a00 0r00000ca0at00n 00r00 00n0rthern
em0an0ment ad0acent t0 C0mm0n0t Health Centre0

Introduction

Safe □ or □ and □ n □ iron □ ents Pty Ltd (S □ □) □ as engaged by Do □ glas Partners to □ nderta □ an Asbestos Clearance Inspection follo □ ing the exca □ tion □ battering and encaps □ lation of in □ sit □ soil containing non □ friable asbestos ce □ ent sheeting fro □ northern e □ ban □ ent located so □ th of the Co □ □ □ nity Health Centre □ The □ or □ s □ ere cond □ cted to facilitate rede □ elop □ ent □ or □ s of Go □ lb □ rn Hospital □ Licenced Asbestos Assessor Da □ id Langston (LAA □ □ □ □ □ □) carried o □ t an inspection of the re □ ocal area follo □ ing co □ pletion of the re □ ocal □ or □ s at □ □ □ p □ on the □ □ □ an □ ary □ □ □ □ □

The scope of `for` included the following

- Visual Inspection of the suspect areas following the asbestos removal or as per the scope of removal and remediation
- Preparation of an Asbestos Clearance Report outlining the site data, conclusions and recommendations (if necessary)

☐ c ☐ e ☐ Rem ☐ a ☐

To excavate and remove from site soils containing asbestos containing material from the northern section of the fleet carpark (as far as practicable) to facilitate building works. Temporarily encapsulate soils remaining in situ suspected of containing asbestos material until further remediation work can occur.

An approximate location of the real world area is included in *Figure 1*

C[][][][][] CLR[][][][] Asbestos Clearance Certificate

a e r and n r n m e t t t d

Site Maors Bay Road

Concord S

Ph Fax

ail en iries s e c o a

Canberra
PO Box
Ph

Inspection Data

Areas inspected within the asbestos removal area by the assessor included

- Visible and accessible surface soils within the northern extension and load off area

During the inspection the assessor noted the northern extension area easement had soils suspected of containing ACM which continues under the property boundary. At the time of inspection the easement area had a temporarily geotextile barrier layer and clean fill to temporarily encapsulate the easement until further excavation and remediation can occur.

No other suspect asbestos material or debris associated with the scope of removal was identified by the assessor during the inspection. Photos of the removal area are included in *Appendix 1*.

Control air monitoring was undertaken during removal. All airborne fibre concentrations were below the reporting limit of 0.001 fibres/L of air.

It is the opinion of the assessor the removal was undertaken by Affectice Services is of appropriate industry standard and in accordance with adopted Code of Practice: *How to Safely Remove Asbestos* (2018).

Conclusion & Recommendations

Based on the data presented in this report it is the opinion of Safe Ironbents Pty Ltd that

- Soils impacted with asbestos containing material within the northern extension have been excavated and temporarily encapsulated where fill was identified.
- The assessor found no visible asbestos debris from asbestos removal work in the area or in the vicinity of the area where the work was carried out.
- It is the opinion of the assessor the inspected area is safe in regards to asbestos to be re-occupied by unprotected persons (providing surface soils are not disturbed).
- Soils within the easement below the barrier horizon are likely to contain asbestos material. Soil disturbance within the area are to occur at a later date and should be undertaken with appropriate asbestos work controls in place (in accordance with the site asbestos management plan).
- If any additional asbestos materials are identified within the site at a later date, work must cease for the asbestos materials to be removed. All asbestos removal of work should be carried out in accordance with the Safe Work Australia 2018 Code of Practice: *How to Safely Remove Asbestos* or as directed by the task specific asbestos safety work procedure.

Should you have any queries regarding this certificate please do not hesitate to contact the undersigned for further information or assistance.

Yours faithfully,

Ironbent Consult
 Maildangston service
 a e r and environment ltd
 PO Box 1111 Dickson ACT 2600
 P 02 6261 1111
www.ironbent.com.au

Attachments
 Figure 1 Asbestos Removal Work Area
 Appendix 1 Site Photographs

CLR 1111 Asbestos Clearance Certificate

a e r and environment ltd
 Site 1111 Maors Bay Road
 Concord NSW 1590
 Ph 02 6261 1111 Fax 02 6261 1111
 Maildangston service

Canberra office
 PO Box 1111 Dickson ACT 2600
 Ph 02 6261 1111

Figure 1 Asbestos Removal Work Area

CLR-1234 Asbestos Clearance Certificate

Safe Work and Environment Ltd
 Site 1234 Maors Bay Road
 Concord NSW 1595
 Phone 02 9999 9999 Fax 02 9999 9999
 Email enquiries@seco.a

Canberra Office
 PO Box 1234 Dickson ACT 2600
 Phone 02 9999 9999



Appendix Site Photographs

Canberra CLR Asbestos Clearance Certificate

Safe Work and Environment Australia
Site 1000s Maors Bay Road
Concord NSW 1590
Ph 02 9339 1000 Fax 02 9339 1001
Email enquiries@seco.a

Canberra Office
PO Box 1000 Dickson ACT 2600
Ph 02 9339 1000



Photograph Prior to additional excavation on the northern extension located south of the Community Health Centre



Photograph Post additional excavation and battering

Completed CLR Asbestos Clearance Certificate

Safe Work and Environment Ltd
Site 1000s Maors Bay Road
Concord NSW
Ph 02 9438 1000 Fax 02 9438 1001
Email enquiries@seco.a

Canberra Office
PO Box 1000 Dickson ACT
Ph 02 9438 1000



Photograph Post excavation and geotextile barrier evident on battered walls note varying depth of excavation to accommodate future site works



Photograph Post excavation and geotextile barrier evident and use of clean fill

Completed CLR Asbestos Clearance Certificate

Safe Work and Environment Ltd
Site 1000s Maors Bay Road
Concord NSW 1592
Ph (02) 9438 1000 Fax (02) 9438 1001
Email enquiries@seco.au

Canberra Office
PO Box 1000 Dickson ACT 2600
Ph (02) 6200 1000

Hansen Yencen Pty Ltd
c/o C-rate Bar
Building 85 O'Riordan Street
Sydney NSW 1571

Project 11111111
11 March 2011
Renee
TBT

Attention: Joel Redmond
c/o Redmond Hansen Yencen Co Ltd

Site Clearance Inspection Piling Area
Goldern Base Hospital
Goldsmith Street Goldern NSW

Introduction

Douglas Partners Pty Ltd (DP) was engaged by Hansen Yencen Pty Ltd (Hansen Yencen) to undertake an asbestos clearance inspection at Goldern Base Hospital Goldsmith Street Goldern NSW (the Site). The clearance inspection was undertaken following piling work that involved excavation of fill containing friable and non-friable asbestos conducted from 11 to 11 March 2011 inclusive.

Tim Bransgrove (Licensed Asbestos Assessor LAA 11111111) of DP observed the piling work and conducted the clearance inspection on 11 March 2011. The clearance inspection was conducted for Work Health and Safety (WHS) purposes in accordance with requirements of the WSHS Regulation 2011 (Regulation 2011 1111).

Area Inspected

The Area Inspected comprised:

- Safely accessible exposed ground surfaces of the piling area as identified approximately on the Site Plan in Attachment A.
- The piling rig.
- The excavator used to transfer asbestos impacted material to waste storage bins.
- The personal decontamination unit.

The Area Inspected excludes:

- The piling holes (inaccessible for safety reasons).

- The asbestos waste bins stockpile and associated storage area (Hansen Yencen reports that this waste is scheduled for off-site disposal on Wednesday 10 March 2010 (approximately))
- The stockpile(s) of “natural” material developed during the piling work which have been sampled by DP. These samples are to undergo analysis for asbestos prior to any disturbance or reuse of the stockpile(s)
- The enclosed water capture and filtration system associated with the personal decontamination unit
- All areas and materials below the exposed ground surface

2 Method

The clearance inspection comprised an unassisted visual examination of safely accessible surfaces within the Area Inspected conducted by a Licensed Asbestos Assessor (LAA)

Airborne asbestos monitoring was undertaken as part of the asbestos removal process and comprised

- 10 March 2010 background monitoring in the Area Inspected prior to piling work
- 10 March 2010 control monitoring around the Area Inspected during piling work
- 10 March 2010 control monitoring around the Area Inspected during restoration (i.e. general cleanup) work and
- 10 March 2010 control monitoring during excavation of a single additional pile and then clearance monitoring in the Area Inspected at completion of all piling work

The air monitoring was conducted in accordance with requirements of the National Occupational Health and Safety Commission (NOHSC) *Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres, 2nd Edition* (NOHSC 10001 (2004)). The laboratory certificate(s) of analysis for the air monitoring are provided in Attachment B

Photographs were taken by DP during the visual inspection and selected photographs are presented in Attachment C

3 Results

Based on the results outlined in the Laboratory Certificate(s) of Analysis (refer Attachment C) the airborne asbestos fibre level was 0.0000 f/m³ L which is the lower reporting limit of the method used. These air monitoring results are considered acceptable for asbestos clearance purposes.

At completion of the visual inspection the assessor found no visible asbestos residue from asbestos removal work in the Area Inspected or in the vicinity of the Area Inspected where the work was carried

Any asbestos contamination that may be present in the water capture and filtration system associated with the personal decontamination unit should be managed in accordance with relevant regulatory requirements including those outlined in the OHS Regulation and CoP.

2. Limitation

This report is provided for the exclusive use of Hansen Yencen for this project only and for the purposes as described in the report. It should not be used by or relied upon for other projects or purposes on the same or other site or by a third party. Any party so relying upon this report beyond its exclusive use and purpose as stated above and without the express written consent of DP does so entirely at its own risk and without recourse to DP for any loss or damage. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

The results provided in the report are indicative of the conditions on the site only at the specific locations inspected and monitored. While work is undertaken in a professional manner the nature of the contaminant and limitations of the method(s) used mean that we cannot guarantee that all asbestos or ACM has been identified.

Inspections and monitoring are limited to areas that are safely accessible at the time of the work and exclude hidden and inaccessible locations such as within stockpiles below the exposed ground surface and within enclosed areas. Any disturbance of the surface(s) inspected may result in the exposure of additional asbestos or ACM that is outside the scope of the visual inspection conducted.

DP's advice is based upon the conditions encountered during this investigation. The accuracy of the advice provided by DP in this report may be affected by undetected variations in conditions across the site between and beyond the inspection and/or monitoring locations. The advice may also be limited by budget constraints imposed by others or by site accessibility.

This report must be read in conjunction with all of the attached and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement/interpretation/opinion or conclusion stated in this report.

This report or sections from this report should not be used as part of a specification for a project without review and agreement by DP. This is because this report has been written as advice and opinion rather than instructions for construction.

DP and our personnel are not licenced quantity surveyors. Any quantities included in this report are provided as a general guide only and should not be relied upon. The services of a licenced quantity surveyor should be engaged if reliable quantities are required.

The inspection(s) conducted do not constitute an Environmental Site Investigation (ESI) under the Contaminated Land Management (CLM) Act. Further testing of soils and other bulk materials pursuant to the National Environmental Protection (Assessment of Site Contamination) Measure (NEMP) may be required to ensure the site is suitable for the proposed land use.

While this report is undertaken in a professional manner DP cannot guarantee that all asbestos/ACM or issues of concern have been identified.

The contents of this report do not constitute formal design components such as are required by the Health and Safety Legislation and Regulations to be included in a Safety Report specifying the hazards likely to be encountered during construction and the controls required to mitigate risk. This design process requires risk assessment to be undertaken with such assessment being dependent upon factors relating to likelihood of occurrence and consequences of damage to property and to life. This in turn requires project data and analysis presently beyond the knowledge and project role respectively of DP. DP may be able however to assist the client in carrying out a risk assessment of potential hazards contained in this report as an extension to the current scope of work if so requested and provided that suitable additional information is made available to DP. Any such risk assessment would however be necessarily restricted to the environmental components set out in this report and to their application by the project designers to project design/construction/maintenance and demolition.

Comments

We trust that the foregoing is of assistance. Please contact the undersigned if you have any queries regarding this matter.

Yours faithfully

Douglas Partners Ltd

Reviewed by

Tim Cranmore

Occupational Hygienist / Environmental Scientist
Licenced Asbestos Assessor (LAA000000)

Tim O'Meara

Associate / Senior Occupational Hygienist
Licenced Asbestos Assessor (LAA000000)



Attachments

- Attachment A – Site Plan
- Attachment B – Laboratory Certificate(s) of Analysis (Air Monitoring)
- Attachment C – Photographic Plates

☐ Attachment ☐

Site Plan

FOR CONTINUATION REFER TO DRG. No. ST-MW-10-00001



KEY PLAN

Rev	Description	Date	By	App
D	FOR CONSTRUCTION - PILING & PILE CAPS ONLY	18/12/18	PM	
H	ISSUED FOR INFORMATION	17/12/18		
G	ISSUED FOR COORDINATION	25/11/18	TJW	
F	ISSUED FOR CONSTRUCTION CERTIFICATE	25/10/18	TJW	
E	100% SUBMISSION	18/10/18	TJW	
D	REISSUED FOR 100% DESIGN DEVELOPMENT	12/06/18	PM	
C	REISSUED FOR 100% DESIGN DEVELOPMENT	29/05/18	PM	
B	100% DESIGN DEVELOPMENT	10/05/18	PM	
A	80% DESIGN DEVELOPMENT	03/05/18	PM	



GOULBURN HOSPITAL
GOULBURN NSW



Bonacci Group (NSW) Pty Ltd
ABN 29 102 716 352
Consulting Engineers, Structural - Civil - Infrastructure
Level 6, 37 York Street, Sydney NSW 2000, Australia
Tel: +61 2 9247 8400 Fax: +61 2 9247 8444
sydney@bonaccigroup.com
www.bonaccigroup.com

FOOTING PLAN
ZONE 2

Project Ref: 11294	
CONSTRUCTION	
Designed: AC	Project Director Approved: Date: North
Drawn: PM	
Scale: 1:100	Drawing No: Rev
Date: 03/05/19	ST-MW-10-00002 0
Sheet: A1	

PAD FOOTING SCHEDULE			
MARK	WIDTH	LENGTH	DEPTH
PF1	1500	1500	400
PF2	2000	2000	450
PF3	1800	2500	450
PF4	1800	1800	450

STRUCTURAL WALL SCHEDULE		
MARK	THICKNESS	REMARKS
BW1	140	FIRE RATED BLOCKWORK (CORE SIZE < 30%)
BW2	190	FIRE RATED BLOCKWORK (CORE SIZE < 30%)
RW1	200	INSITU RW
RW2	350	INSITU RW
RW3	250	INSITU RW
W1	200	INSITU
W3	150	INSITU

STRIP FOOTING SCHEDULE		
MARK	DIMENSIONS	
	WIDTH	DEPTH
SF1	1200	600
SF2	600	450
SF3	450	600
SF4	1800	450

FOOTING PLAN - ZONE 2

SCALE: 1:100
REFER SHEET ST-MW-30-00010 FOR STEEL MEMBER FRAMING SCHEDULE

PILING SCHEDULE							
MARK	SIZE	G (kN)	Q (kN)	SHEAR X (ULT) (kN)	SHEAR Y (ULT) (kN)	TENSION (ULT) (kN)	COMP (ULT) (kN)
P1	450	150	90	10	10	-	315
P2	900	1200	450	60	60	-	2150
P3	900	1600	550	70	70	-	2750
P4	900	1550	650	80	80	-	2650
P5	900	3000	1250	150	150	-	5475
P6	900	3450	1350	160	160	-	6175
P7	900	1900	800	90	90	-	3500
P8	900	1000	250	600	400	-3400	4750
P9	900	1000	250	450	400	-2100	3650
P10	900	1800	400	400	500	-2900	5350
P11	900	1500	500	400	400	-1250	3250
P12	900	1200	400	500	600	-450	2500
P13	900	850	300	500	250	-1400	2200
P14	450	450	90	100	100	-	700
P15	450	300	120	15	15	-	550
P16	450	150	120	10	10	-	375
P17	900	500	250	500	500	-1100	1500
P18	450	200	125	15	15	-	450

NOTE:
ALTERNATIVE PAD FOOTING SIZES ARE BASED ON EXTREMELY LOW STRENGTH ROCK (DENOTED 'EL' IN BOREHOLE LOGS) AS THE FOUNDING STRATA WITH ALLOWABLE BEARING PRESSURE (ABP) = 600 kPa. WHERE LOW STRENGTH ROCK (DENOTED 'L' IN BOREHOLE LOGS) IS THE FOUNDING STRATA, ALLOWABLE BEARING PRESSURE (ABP) = 1000 kPa AND THE PAD FOOTING SIZE MAY BE REDUCED.

☐ **Attachment** ☐

Laboratory Certificate(s) of Analysis
(Air Monitoring)



□□ail□en□□re□□ec□ma□

□□□□T□□ □□R□ C□□□T□G R□□□□T□

□□ March □□□□

□na□□ed and re□□rted □□□



□ared □arne□

Analyst and Appro□ed Iss□er of Report



□Period of Sa□pling defined by the on□□e of the first air □onitoring sa□ple to the off□□e of the last air □onitoring sa□ple□

C□□□□□AAM□□□□AsbestosAirMonitoringReport

□a□e □ □r□and □n□r□nment□ □t□ □td □□□□□□□□□□

S□te S□□□□Dic□son Cha□bers□Dic□son Place□Dic□son ACT □□□□

Phone□□□ □□□□ □□□□

□□ail□en□□□re□□ □□e□c□m□a□

Accredited for compliance
with ISO 11177
Testing

□□□□T□ □□R C□□T□G R□□□T□

□□ March □□□□

tentn Ti ar
Cman Doglas Partners
ma ti ar doglaspartners.coa

☐ ☐ ☐ **Report Reference** C ☐☐☐☐☐☐ AAM ☐☐☐☐☐☐
☐ **File Address** ☐☐☐☐☐☐
☐ **Name Received From** T ☐ Bransgrove ☐ Douglas Partners
☐ **Dating Date** ☐☐ March ☐☐☐
☐ **Period Dating** ☐☐☐☐ – ☐☐☐☐
☐ **Name Entered Date** ☐☐ March ☐☐☐
☐ ☐ ☐ **Author(s)** S ☐ite S ☐☐☐☐ Dic ☐son Cha ☐bers ☐Dic ☐son Place ☐Dic ☐son ACT ☐☐
 S ☐ ☐ Field Laboratory – C ☐☐☐☐☐☐

ccredfatiin nmer

Introduction Control monitoring for airborne asbestos fibres were collected by Douglas Partners and submitted to the Safe Work and Environment Laboratory for analysis by the membrane filter count and count methodology.

Method Airborne asbestos fibre monitoring was carried out by Douglas Partners and samples analysed as received. Analysis of collected filter membrane samples was performed in accordance with OHSC:3003 (2005) and SWE's In-Home Method – Asbestos Air Fibre Count and Count.

Reft

[illegible]

□Period of Sa□pling defined by the on□□□e of the first air □□□□□□ sa□ple to the off□□□e of the last air □□□□□□ sa□ple□

C A A M Asbestos Air Monitoring Report

Page 1 of 1

aae r and n r nment t td
 Site S Dic Son Cha bers Dic Son Place Dic Son ACT
 Phone
 ail en re e c ma

□□□□T□□ □□R□ C□□□T□G R□□□□T□

□□ March □□□□

□na□□ed and re□□rted □□□



□ared □arne□

Analyst and Appro□ed Iss□er of Report



□Period of Sa□pling defined by the on□□e of the first air □onitoring sa□ple to the off□□e of the last air □onitoring sa□ple□

C□□□□□AAM□□□AsbestosAirMonitoringReport □□□□□□

□a□e □ □r□and □n□r□nment□ □t□ □td □□□□□□□□□□

S□te S□□□□Dic□son Cha□bers□Dic□son Place□Dic□son ACT □□□□

Phone□□□ □□□□ □□□□

□□ail□en□□□re□□ □□e□c□m□a□



ASBESTOS MONITORING REPORT

11 March 2020

Attention

Companion

Manager

Tim Bransgrove

Douglas Partners

tim.bransgrove@douglaspartners.co.au



WORLD RECOGNISED
ACCREDITATION

Accredited for compliance
with ISO 17025:2017
Testing

Report Reference

CAM-2020-0001

Site Address

100/100

Sample Received From

Tim Bransgrove Douglas Partners

Sampling Date

11 March 2020

Period of Sampling

08:00 – 16:00

Sample Name Date

11 March 2020

Site Location

Site 100/100 Dickson Chambers Dickson Place Dickson ACT 2600

Site 1 Field Laboratory – CAM-2020-0001

Accreditation Number

100/100

Site Number

100/100

Introduction Control monitoring for airborne asbestos fibres were collected by Douglas Partners and submitted to the Safe Work and Environment Laboratory for analysis by the membrane filter count and count methodology

Method

Airborne asbestos fibre monitoring was carried out by Douglas Partners and samples analysed as received. Analysis of collected filter membrane samples was performed in accordance with OHSC (2015) and SWE's In-House Method – Asbestos Air Fibre Count and Count

Results

Site Location	Count Method Detail	Result
Corner of 100/100	South eastern corner of 100/100 area on fence	100/100
Corner of 100/100	South western corner of 100/100 area on fence	100/100
Corner of 100/100	North eastern corner of 100/100 area on fence	100/100
Corner of 100/100	North central boundary on fence	100/100
Corner of 100/100	Clean side of decontamination door	100/100
Corner of 100/100	Field Control (Blank)	100/100

Analysed and reported by

Analyst Name

Analyst and Approved Issuer of Report

Period of Sampling defined by the on/off of the first air monitoring sample to the on/off of the last air monitoring sample

CAM-2020-0001 Asbestos Air Monitoring Report 100/100

Page 1 of 1

Safe Work and Environment Ltd 100/100

Site 100/100 Dickson Chambers Dickson Place Dickson ACT 2600

Phone 100/100 100/100

Email 100/100@100/100.com.au

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 709306-AFC
Project Name GOULBURN HOSPITAL
Project ID 94054.06
Received Date Mar 23, 2020
Date Reported Mar 23, 2020

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID 94054.06
Date Sampled Mar 23, 2020
Report 709306-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
20-Ma33197	DL010239	DP19	SOUTH EAST CORNER OF WORK AREA, ON FENCE	7:10	11:20	4.0	4.0	0/100	< 0.01
20-Ma33198	DL010228	DP04	SOUTHERN CENTRAL BOUNDARY OF WORK AREA, ON FENCE	7:10	11:29	4.0	4.0	0/100	< 0.01
20-Ma33199	DL010338	DP11	SOUTH WESTERN CORNER OF WORK AREA, ON FENCE	7:10	11:29	4.0	4.0	0/100	< 0.01
20-Ma33200	DL010446	DP12	NORTH WESTERN CORNER OF WORK AREA, ON FENCE	7:11	11:31	4.0	4.0	0/100	< 0.01
20-Ma33201	DL010169	DP03	NORTHERN CENTRAL BOUNDARY OF WORK AREA, ON FENCE	7:12	11:27	4.0	4.0	0/100	< 0.01
20-Ma33202	DL010559	DP15	NORTH EASTERN CORNER OF WORK AREA, ON FENCE	7:13	11:26	4.0	4.0	0/100	< 0.01
20-Ma33203	DL010511	DP09	CLEAN SIDE OF DECON UNIT ON DOOR	7:12	11:25	4.0	4.0	0/100	< 0.01

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Mar 23, 2020	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Mar 23, 2020	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054.06

Order No.:
Report #: 709306
Phone: 02 9809 0666
Fax:

Received: Mar 23, 2020 1:50 PM
Due: Mar 23, 2020
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail

Asbestos (concentration of fibres in air)

Melbourne Laboratory - NATA Site # 1254 & 14271

Sydney Laboratory - NATA Site # 18217

Brisbane Laboratory - NATA Site # 20794

Perth Laboratory - NATA Site # 23736

External Laboratory

No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	DL010239	Mar 23, 2020	11:30AM	Air	S20-Ma33197	X
2	DL010228	Mar 23, 2020	11:29AM	Air	S20-Ma33198	X
3	DL010338	Mar 23, 2020	11:29AM	Air	S20-Ma33199	X
4	DL010446	Mar 23, 2020	11:31AM	Air	S20-Ma33200	X
5	DL010169	Mar 23, 2020	11:27AM	Air	S20-Ma33201	X
6	DL010559	Mar 23, 2020	11:26AM	Air	S20-Ma33202	X
7	DL010511	Mar 23, 2020	11:25AM	Air	S20-Ma33203	X
Test Counts						7

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED], Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins Environment Testing and therefore volume measurements contained in this report are traceable back to Eurofins Environment Testing. Eurofins Environment Testing are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	N/A
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised [REDACTED]

[REDACTED] Senior Analyst-Asbestos (NSW)

General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Douglas Partners (Syd)
96 Hermitage Road
West Ryde
NSW 2114



NATA Accredited
Accreditation Number 1261
Site Number 18217

Accredited for compliance with ISO/IEC 17025-Testing
The results of the tests, calibrations and/or
measurements included in this document are traceable
to Australian/national standards.

Attention: [REDACTED]
Report 709298-AFC
Project Name GOULBURN HOSPITAL
Project ID 94054.06
Received Date Mar 23, 2020
Date Reported Mar 23, 2020

METHODOLOGY:

Asbestos Sampling	Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]
Pump Calibration	Defender 520M: Calibrated against National Institute of Standards & Technology (NIST) SOP 13 Standard Operating Procedure for Calibration of Volumetric Ware, Gravimetric Method utilising a 1000 mL burette with a digital stop watch.
Asbestos Counting	Conducted in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and in-house Method LTM-ASB-8010.

Project Name GOULBURN HOSPITAL
Project ID 94054.06
Date Sampled Mar 23, 2020
Report 709298-AFC

Eurofins Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Result (Fibres/Fields)	Result (Fibres/mL)
20-Ma33147	DL010340	DP01	EASTERN CENTRE OF WORK AREA, ON POLE	9:03	11:30	4.0	4.0	0/100	< 0.01
20-Ma33148	DL010165	DP04	WESTERN CENTRE OF WORK AREA, ON POLE	9:05	11:29	4.0	4.0	0/100	< 0.01
20-Ma33149	DL010232	DP07	INSIDE DECONTAMINATION UNIT	9:05	11:28	4.0	4.0	0/100	< 0.01
20-Ma33150	DL010342	DP02	INSIDE CABIN OF PILING RIG	9:05	11:28	4.0	4.0	0/100	< 0.01
20-Ma33151	DL010382	DP18	INSIDE CABIN OF EXCAVATOR	9:07	11:27	4.0	4.0	0/100	< 0.01

Sample History

Where samples are submitted/analysed over several days, the last date of extraction and analysis is reported. A recent review of our LIMS has resulted in the correction or clarification of some method identifications. Due to this, some of the method reference information on reports has changed. However, no substantive change has been made to our laboratory methods, and as such there is no change in the validity of current or previous results.

If the date and time of sampling are not provided, the Laboratory will not be responsible for compromised results should testing be performed outside the recommended holding time.

Description	Testing Site	Extracted	Holding Time
Asbestos - LTM-ASB-8010	Sydney	Mar 23, 2020	Indefinite
Asbestos - LTM-ASB-8010	Sydney	Mar 23, 2020	Indefinite

Company Name: Douglas Partners (Syd)
Address: 96 Hermitage Road
West Ryde
NSW 2114

Project Name: GOULBURN HOSPITAL
Project ID: 94054.06

Order No.:
Report #: 709298
Phone: 02 9809 0666
Fax:

Received: Mar 23, 2020 1:50 PM
Due: Mar 23, 2020
Priority: Same day
Contact Name: [REDACTED]

Eurofins Analytical Services Manager : [REDACTED]

Sample Detail

Asbestos (concentration of fibres in air)

Melbourne Laboratory - NATA Site # 1254 & 14271

Sydney Laboratory - NATA Site # 18217

Brisbane Laboratory - NATA Site # 20794

Perth Laboratory - NATA Site # 23736

External Laboratory

No	Sample ID	Sample Date	Sampling Time	Matrix	LAB ID	
1	DL010340	Mar 23, 2020	11:30AM	Air	S20-Ma33147	X
2	DL010165	Mar 23, 2020	11:29AM	Air	S20-Ma33148	X
3	DL010232	Mar 23, 2020	11:28AM	Air	S20-Ma33149	X
4	DL010342	Mar 23, 2020	11:28AM	Air	S20-Ma33150	X
5	DL010382	Mar 23, 2020	11:27AM	Air	S20-Ma33151	X

Test Counts

5

Internal Quality Control Review and Glossary

General

1. QC data may be available on request.
2. All soil results are reported on a dry basis, unless otherwise stated.
3. Samples were analysed on an 'as received' basis.
4. Information identified on this report with blue colour, indicates data provided by customer, that may have an impact on the results.
5. This report replaces any interim results previously issued.

Holding Times

Please refer to 'Sample Preservation and Container Guide' for holding times (QS3001).

For samples received on the last day of holding time, notification of testing requirements should have been received at least 6 hours prior to sample receipt deadlines as stated on the Sample Receipt Advice.

If the Laboratory did not receive the information in the required timeframe, and regardless of any other integrity issues, suitably qualified results may still be reported.

Holding times apply from the date of sampling, therefore compliance to these may be outside the laboratory's control.

Units

% w/w	weight for weight basis	grams per kilogram
Filter loading:		fibres/100 graticule areas
Reported Concentration:		fibres/mL
Flowrate:		L/min

Terms

Dry	Sample is dried by heating prior to analysis
LOR	Limit of Reporting
COC	Chain of Custody
SRA	Sample Receipt Advice
ISO	International Standards Organisation
AS	Australian Standards
WA DOH	Reference document for the NEPM. Government of Western Australia, Guidelines for the Assessment, Remediation and Management of Asbestos-Contaminated Sites in Western Australia (2009), including supporting document Recommended Procedures for Laboratory Analysis of Asbestos in Soil (2011)
NEPM	National Environment Protection (Assessment of Site Contamination) Measure, 2013 (as amended)
ACM	Asbestos Containing Materials. Asbestos contained within a non-asbestos matrix, typically presented in bonded and/or sound condition. For the purposes of the NEPM, ACM is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
AF	Asbestos Fines. Asbestos containing materials, including friable, weathered and bonded materials, able to pass a 7mm x 7mm sieve. Considered under the NEPM as equivalent to "non-bonded / friable".
FA	Fibrous Asbestos. Asbestos containing materials in a friable and/or severely weathered condition. For the purposes of the NEPM, FA is generally restricted to those materials that do not pass a 7mm x 7mm sieve.
Friable	Asbestos-containing materials of any size that may be broken or crumbled by hand pressure. For the purposes of the NEPM, this includes both AF and FA. It is outside of the laboratory's remit to assess degree of friability.
Trace Analysis	Analytical procedure used to detect the presence of respirable fibres in the matrix.

Comments

Volume Measurement : [REDACTED] Douglas Partners (Syd), has been trained by Eurofins and they conducted the sampling in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] methodology. Sampling pumps used by Douglas Partners (Syd) were calibrated by Eurofins Environment Testing and therefore volume measurements contained in this report are traceable back to Eurofins Environment Testing. Eurofins Environment Testing are responsible for all data contained in this report.

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	N/A
Sample correctly preserved	Yes
Appropriate sample containers have been used	Yes
Sample containers for volatile analysis received with minimal headspace	N/A
Samples received within HoldingTime	Yes
Some samples have been subcontracted	No

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Asbestos Counter/Identifier:

[REDACTED] Senior Analyst-Asbestos (NSW)

Authorised [REDACTED]

Sayeed Abu Senior Analyst-Asbestos (NSW)



General Manager

Final Report – this report replaces any previously issued Report

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Measurement uncertainty of test data is available on request or please [click here](#).

Eurofins shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.

Attachment C


Photographic Plates



Photograph □□ Typical portion of Area Inspected following piling □ or □□



Photograph □□ Area Inspected as viewed from □ west to east following piling □ or □□


 Douglas Partners Geotechnics Environment Groundwater	Site Photograph	PROJECT □ □ □ □ □ □ □ □
	Street Clearance Inspection	PLAT □ □ □ □ □
	Government of Western Australia Redevelopment	ROAD A
	CLIENT Hansen Yncen Pty Ltd	DATE □ □ □ □ □ □ □ □



Photograph □□ Typical portion of Area Inspected (left hand side of photo) following piling
□ or □



Photograph □□ Waste bin storage area □


	Site Photograph	PROJECT
	Clearance Inspection	PLAT
	Ground Base Holes Remediation	R
	CLIENT Hansen Yncen Pty Ltd	DAT



Photograph □□Piling rig□



Photograph □□Asbestos waste stockpile excluded from clearance inspection□


 Douglas Partners Geotechnics Environment Groundwater	Site Photograph	PROJECT □□□□□□□□
	Pre-Clearance Inspection	PLANT □□□ □
	Government of Western Australia Redevelopment	ROOM A
	CLIENT Hansen Yanco Pty Ltd	DATE □□□□□□□□



Photograph of Decontamination Unit



Photograph of Typical portion of bulk material transport route


 Douglas Partners Geotechnics Environment Groundwater	Site Photograph	PROJECT
	Obtained Clearance Inspection	PLANT
	Groundwater Base Hazard Remediation	ROOM A
	CLIENT Hansen Yencen Pty Ltd	DATE



Photograph □□Typical piling hole□



Photograph □□Stoc□piles excl□ded fro□ □is□al clearance□

 Douglas Partners Geotechnics Environment Groundwater	□ite □h□t□graph□	PRO□ECT□ □□□□□□□
	□□□e□□ Clearance □□□ect□□□	PLAT□ □o□ □
	G□□□□□□□ □a□e H□□□□ta□ Rede□e□□□□□□□	R□□□ A
	CL□□□□ Hansen Y□nc□en Pty Ltd	DAT□□ □□□□□□□□

Memorandum

To	[REDACTED]	Hansen Yuncken Pty Ltd	egodfrey@hansenyuncken.com.au
From	[REDACTED]	Date	29 Jan 2020
Subject	Vibration Monitoring Report 1 Goulburn Base Hospital Redevelopment		Project No. 94054.07 Doc. No. 94054.07.R.001.Rev0

Installation and Monitoring

On 9 December 2019 Texcel Construction Vibration Monitors #7221 and #7153 were installed at ground level at monitoring locations A (adjacent to the community health centre) and B (adjacent to the nearest hospital building), respectively (see attached Monitor Location Plan). The monitors were installed to monitor vibrations generated during compaction works in the adjacent borrow pit.

With reference to the CNVMP, an "Allowed Vibration Limit" of 5 mm/s vector sum peak particle velocity (VSPPV) was assigned by DP, based on the potential for damage to the adjacent structures and the comfort of the occupants. The monitors were configured for continuous monitoring 6 am - 6 pm Mon - Sat, with SMS (text message) alarms to be sent automatically to Eugene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 4.5 mm/s VSPPV, as a contingency for the Allowed Limit of 5 mm/s VSPPV).

Monitoring was suspended on 13 January 2020 upon completion of compaction works in the borrow pit.

Outcome this period: 9-December 2019 to 13-January 2020

Location	Monitor	Exceedances		Time of maximum exceedance
		No.	Max (VSPPV)	
Monitoring Location A	7221	0	n/a	n/a
Monitoring Location B	7153	0	n/a	n/a

Douglas Partners Pty Ltd



Senior Geophysicist

Reviewed by



Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Limitations


Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yuncken Pty Ltd. The report is provided for the exclusive use of Hansen Yuncken Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.


DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time. Vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.


The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.


As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yuncken Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, re-installation and/or repair is required.


This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.















Monitor
7153

Vibration Levels - Goulburn Hospital Redevelopment (Monitoring Location B)









About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason they must be regarded as interpretive rather than factual documents limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Overview and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days or perhaps weeks for low permeability soils. Piezometers sealed in a particular stratum may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel based on the information obtained from field and laboratory testing and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal the information and interpretation may not be relevant if the design proposal is changed. If this happens DP will be pleased to revise the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects and recommendations or suggestions for design and construction. However DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities or
- The actions of contractors responding to commercial pressures.

If these occur DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	Gene Godfrey	Hansen Yencen Pty Ltd	egodfrey@hansenyencen.co.au
From	Anthony Ielniac	Date	11 Feb 2015
Subject	Vibration Monitoring Report for Goldbarn Base Hospital Redevelopment		Project 111 11111111 Doc 111 111 11111111R1111Re111

Information and Monitoring

On 11 January 2015 Texcel Construction Vibration Monitors 111111 111111 were relocated to the positions shown in the attached Monitoring Location Plan before the start of a staged piling. Both monitors were coupled to the ground with a scharge close to and at ground level of the adjacent building which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works.

With reference to the CEMP (the Monitoring Plan) "Allowed Vibration Limits" of 0.005 ms⁻² peak particle velocity (PPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Rate (VDR) of 0.005 ms⁻² for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon-Sat and 9pm with SMS (text message) alarms to be sent automatically to Gene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 0.005 ms⁻² PPV as a contingency for impulsive events).

The VDR shown in the attached graphs is a calculated estimate of VDR from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities and amplitudes (as detailed in SSPA Assessing Vibration A Technical Guideline February 2004). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring and these criteria are indicative only therefore consideration of continuous and impulsive vibrations is included (as recommended) see attached graphs. The table of acceptable daily Dose Rates Table 1111 includes a "Preferred Value", being half of the "Maximum Value".

Outcome threshold 0.005 ms⁻² PPV

Location	Monitor	Exceedance		Time Maximum Exceedance
		111	Maximum	
Monitoring Location A	1111	0	na	na
Monitoring Location B	1111	0	na	na

Douglas Partners Ltd

Anthony Mac

Senior Geophysicist

Reviewed by

Peter Tmaa

Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan About This Report

Statement

Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yncen Pty Ltd. The report is provided for the exclusive use of Hansen Yncen Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.


The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.

As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the responsibility of vibration remains the responsibility of Hansen Yncen Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, reinstallation and/or repair is required.

This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement/interpretation or conclusion or conclusion given in this report.


**Monitor
7153**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)




Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location B - NE-cnr of pathology-mortuary building)

Monitor
7153




Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)


Monitor
7221



Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)

Monitor
7221





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason they must be regarded as interpretive rather than factual documents limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Reference and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days or perhaps weeks for low permeability soils. Piezometers sealed in a particular stratum may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel based on the information obtained from field and laboratory testing and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal the information and interpretation may not be relevant if the design proposal is changed. If this happens DP will be pleased to revise the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects and recommendations or suggestions for design and construction. However, DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities or
- The actions of contractors responding to commercial pressures.

If these occur DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	Gene Godfrey	Hansen Yencen Pty Ltd	egodfrey@hansenyencen.co.au
From	Anthony Ielniac	Date	11 Feb 2015
Subject	Vibration Monitoring Report for Goldbarn Base Hospital Redevelopment		Project 100 100000000 Doc 100 100000000R1000Re

Information and Monitoring

On 11 January 2015 Texcel Construction Vibration Monitors were relocated to the positions shown in the attached Monitoring Location Plan before the start of a staged piling. Both monitors were coupled to the ground with a scharge close to and at ground level of the adjacent building which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works.

With reference to the CEMP (the Monitoring Plan) "Allowed Vibration Limits" of 0.1 ms⁻² vector s_{pea} particle velocity (v_{SPP}) was assigned by DP based on the potential for damage to the adjacent structures and a vibration Dose Rate (v_{DR}) of 0.1 ms⁻² for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon-Sat and 9pm with SMS (text message) alarms to be sent automatically to Gene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 0.1 ms⁻² v_{SPP} as a contingency for impulsive events).

The v_{DR} shown in the attached graphs is a calculated estimate of v_{DR} from velocity data rather than acquired acceleration data. The Dose Rate and Maximum values refer to acquired vibration activity per day during daytime hours and includes summations of RMS velocities, a length durations and amplitudes (as detailed in v_{DR} v_{PA} Assessing Vibration A Technical Guideline February 2014). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring and these criteria are indicative only therefore consideration of continuous and impulsive vibrations is included (as recommended) see attached graphs. The table of acceptable daily Dose Rates Table 1000 includes a "Preferred Value", being half of the "Maximum Value".

Outcome the recorded 100 linear 100 error 1000

Location	Monitor	Exceedance		Time Maximum Exceedance
		100	Maximum	
Monitoring Location A	1000	1	na	na
Monitoring Location B	1000	1	na	na

Douglas Partners Ltd

Reviewed by

Anthony Mac

Senior Geophysicist

Peter Tmaa

Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Statement

Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yncen Pty Ltd. The report is provided for the exclusive use of Hansen Yncen Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.


The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.

As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the responsibility of management of vibration remains the responsibility of Hansen Yncen Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, reinstallation and/or repair is required.

This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement/interpretation or conclusion or conclusion given in this report.


Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)

Monitor
7153




Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location B - NE-cnr of pathology-mortuary building)

Monitor
7153




Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)


Monitor
7221



Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)

Monitor
7221





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason, they must be regarded as interpretive rather than factual documents, limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Reference and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions, and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment, but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling, and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems, namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days, or perhaps weeks for low permeability soils. Piezometers, sealed in a particular stratum, may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel, is based on the information obtained from field and laboratory testing, and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal, the information and interpretation may not be relevant if the design proposal is changed. If this happens, DP will be pleased to revise the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects, and recommendations or suggestions for design and construction. However, DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities.
- The actions of contractors responding to commercial pressures.

If these occur, DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	Gene Godfrey	Hansen Yencen Pty Ltd	egodfrey@hansenyencen.co.au
From	Anthony Ielniac	Date	11 Feb 2015
Subject	Vibration Monitoring Report for Goldbarn Base Hospital Redevelopment		Project 111 11111111 Doc 111 111 11111111R1111Re111

Information and Monitoring

On 11 January 2015 Texcel Construction Vibration Monitors were relocated to the positions shown in the attached Monitoring Location Plan before the start of a staged piling. Both monitors were coupled to the ground with a scribe close to and at ground level of the adjacent building which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works.

With reference to the CEMP (the Monitoring Plan) "Allowed Vibration Limits" of 0.1 ms⁻² vector sum peak particle velocity (PPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Rate (VDR) of 0.1 ms⁻² for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon-Sat and 9pm with SMS (text message) alarms to be sent automatically to Gene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 0.1 ms⁻² PPV as a contingency for immediate events).

The VDR shown in the attached graphs is a calculated estimate of VDR from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities, a length durations and amplitudes (as detailed in ISO 2631-1:1997 Assessing Vibration - A Technical Guide February 2000). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring and these criteria are indicative only; therefore consideration of continuous and immediate vibrations is included (as recommended) see attached graphs. The table of acceptable daily Dose Rates Table 1 includes a "Preferred Value", being half of the "Maximum Value".

Outcome threshold error

Location	Monitor	Exceedance		Time Maximum Exceedance
		111	Maximum	
Monitoring Location A	1111	1	na	na
Monitoring Location B	1111	1	na	na

Douglas Partners Ltd

Reviewed by

Anthony Enac

Senior Geophysicist

Peter Tmaa

Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan About This Report

Statement

Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yncen Pty Ltd. The report is provided for the exclusive use of Hansen Yncen Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.


The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.

As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yncen Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, reinstallation and/or repair is required.

This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement/interpretation or conclusion or conclusion given in this report.


**Monitor
7153**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)




Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location B - NE-cnr of pathology-mortuary building)

Monitor
7153




Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)

Monitor
7221



Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)

Monitor
7221





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason, they must be regarded as interpretive rather than factual documents, limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Reference and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions, and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment, but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling, and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems, namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days, or perhaps weeks for low permeability soils. Piezometers, sealed in a particular stratum, may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel, is based on the information obtained from field and laboratory testing, and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal, the information and interpretation may not be relevant if the design proposal is changed. If this happens, DP will be pleased to revise the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects, and recommendations or suggestions for design and construction. However, DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities.
- The actions of contractors responding to commercial pressures.

If these occur, DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	██████████ Hansen Yuncken Pty Ltd ██████████ u
From	██████████
Date	17 Mar 2020
Subject	Vibration Monitoring Report 5 Goulburn Base Hospital Redevelopment
Project No.	94054.07
Doc. No.	94054.07.R.005.Rev0

Installation and Monitoring

On 21 January 2020 Texcel Construction Vibration Monitors #7221, #7153 were relocated to the positions shown in the attached Monitoring Location Plan, before the start of augered piling. Both monitors were coupled to the ground with a surcharge, close to and at ground level of the adjacent building, which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works.

With reference to the CNVMP (the Monitoring Plan), an "Allowed Vibration Limit" of 25 mm/s vector sum peak particle velocity (VSPPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Value (VDV) of 0.20 m/s^{1.75} for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon - Sat, 6 am - 6 pm, with SMS (text message) alarms to be sent automatically to Eugene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 7 mm/s VSPPV, as a contingency for impulsive events).

The eVDV shown in the attached graphs is a calculated estimate of VDV from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities, wavelength durations and amplitudes (as detailed in NSW EPA Assessing Vibration: A Technical Guideline, February 2006). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring, and these criteria are indicative only, therefore consideration of continuous and impulsive vibrations is included (as recommended), see attached graphs. The table of acceptable daily Dose Values, Table 2.4, includes a "Preferred Value", being half of the "Maximum Value".

Outcome this period: 10 - 17 February 2020

Location	Monitor	Exceedances		Time of maximum exceedance
		No.	Max (VSPPV)	
Monitoring Location A	7221*	n/a	n/a	n/a
Monitoring Location B	7153	0	n/a	n/a

*No data recorded by monitor #7221 for the period.

Douglas Partners Pty Ltd[REDACTED]
[REDACTED]
Senior Geophysicist

Reviewed by

[REDACTED]
[REDACTED]
Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Limitations


Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yuncken Pty Ltd. The report is provided for the exclusive use of Hansen Yuncken Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time. Vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.

The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.

As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yuncken Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, re-installation and/or repair is required.


This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.



**Monitor
7153**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason, they must be regarded as interpretive rather than factual documents, limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Overview and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions, and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment, but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling, and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems, namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days, or perhaps weeks for low permeability soils. Piezometers, sealed in a particular stratum, may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel, is based on the information obtained from field and laboratory testing, and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal, the information and interpretation may not be relevant if the design proposal is changed. If this happens, DP will be pleased to revise the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects, and recommendations or suggestions for design and construction. However, DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities or
- The actions of contractors responding to commercial pressures.

If these occur, DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	██████████	Hansen Yuncken Pty Ltd	██████████
From	██████████	Date	17 Mar 2020
Subject	Vibration Monitoring Report 6 Goulburn Base Hospital Redevelopment		Project No. 94054.07 Doc. No. 94054.07.R.006.Rev0

Installation and Monitoring

On 21 January 2020 Texcel Construction Vibration Monitors #7221, #7153 were relocated to the positions shown in the attached Monitoring Location Plan, before the start of augered piling. Both monitors were coupled to the ground with a surcharge, close to and at ground level of the adjacent building, which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works.

With reference to the CNVMP (the Monitoring Plan), an "Allowed Vibration Limit" of 25 mm/s vector sum peak particle velocity (VSPPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Value (VDV) of 0.20 m/s^{1.75} for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon - Sat, 6 am - 6 pm, with SMS (text message) alarms to be sent automatically to Eugene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 7 mm/s VSPPV, as a contingency for impulsive events).

The eVDV shown in the attached graphs is a calculated estimate of VDV from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities, wavelength durations and amplitudes (as detailed in NSW EPA Assessing Vibration: A Technical Guideline, February 2006). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring, and these criteria are indicative only, therefore consideration of continuous and impulsive vibrations is included (as recommended), see attached graphs. The table of acceptable daily Dose Values, Table 2.4, includes a "Preferred Value", being half of the "Maximum Value".

Outcome this period: 17 - 24 February 2020

Location	Monitor	Exceedances		Time of maximum exceedance
		No.	Max (VSPPV)	
Monitoring Location A	7221*	n/a	n/a	n/a
Monitoring Location B	7153	0	n/a	n/a

*No data recorded by monitor #7221 for the period.

Douglas Partners Pty Ltd



Senior Geophysicist

Reviewed by



Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Limitations


Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yuncken Pty Ltd. The report is provided for the exclusive use of Hansen Yuncken Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time. Vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.

The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.


As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yuncken Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, re-installation and/or repair is required.


This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.



**Monitor
7153**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason, they must be regarded as interpretive rather than factual documents, limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Reference and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions, and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment, but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling, and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems, namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water measurements are to be made.

More reliable measurements can be made by installing standpipes which are read at intervals over several days, or perhaps weeks for low permeability soils. Piezometers, sealed in a particular stratum, may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel, is based on the information obtained from field and laboratory testing, and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal, the information and interpretation may not be relevant if the design proposal is changed. If this happens, DP will be pleased to reissue the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects, and recommendations or suggestions for design and construction. However, DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities.
- The actions of contractors responding to commercial pressures.

If these occur, DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	[REDACTED]	Hansen Yuncken Pty Ltd	[REDACTED]
From	[REDACTED]	Date	17 Mar 2020
Subject	Vibration Monitoring Report 7 Goulburn Base Hospital Redevelopment		Project No. 94054.07 Doc. No. 94054.07.R.007.Rev0

Installation and Monitoring

On 21 January 2020 Texcel Construction Vibration Monitors #7221, #7153 were relocated to the positions shown in the attached Monitoring Location Plan, before the start of augered piling. Both monitors were coupled to the ground with a surcharge, close to and at ground level of the adjacent building, which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works. On 26 February 2020, Monitor #7221 was replaced with Omnidot Vibration Monitor "Vujaca".

With reference to the CNVMP (the Monitoring Plan), an "Allowed Vibration Limit" of 25 mm/s vector sum peak particle velocity (VSPPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Value (VDV) of 0.20 m/s^{1.75} for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon - Sat, 6 am - 6 pm, with SMS (text message) alarms to be sent automatically to Eugene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 7 mm/s VSPPV, as a contingency for impulsive events).

The eVDV shown in the attached graphs is a calculated estimate of VDV from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities, wavelength durations and amplitudes (as detailed in NSW EPA Assessing Vibration: A Technical Guideline, February 2006). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring, and these criteria are indicative only, therefore consideration of continuous and impulsive vibrations is included (as recommended), see attached graphs. The table of acceptable daily Dose Values, Table 2.4, includes a "Preferred Value", being half of the "Maximum Value".

Outcome this period: 24 February to 2 March 2020

Location	Monitor	Exceedances		Time of maximum exceedance
		No.	Max (VSPPV)	
Monitoring Location A	7221/Vujaca	0	n/a	n/a
Monitoring Location B	7153	0	n/a	n/a

Douglas Partners Pty Ltd



Senior Geophysicist

Reviewed by



Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Limitations

Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yuncken Pty Ltd. The report is provided for the exclusive use of Hansen Yuncken Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time. Vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.


The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.

As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yuncken Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, re-installation and/or repair is required.

This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.


Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location B - NE-cnr of pathology-mortuary building)


Monitor
7153



**Monitor
7153**


Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)






**Monitor
VUJACA**


**Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)**



**Monitor
VUJACA**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason, they must be regarded as interpretive rather than factual documents, limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Overview and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions, and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment, but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling, and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems, namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days, or perhaps weeks for low permeability soils. Piezometers, sealed in a particular stratum, may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel, is based on the information obtained from field and laboratory testing, and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal, the information and interpretation may not be relevant if the design proposal is changed. If this happens, DP will be pleased to revise the report and the sufficiency of the investigation or of

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects, and recommendations or suggestions for design and construction. However, DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities or
- The actions of contractors responding to commercial pressures.

If these occur, DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	[REDACTED]	Hansen Yuncken Pty Ltd	[REDACTED]
From	[REDACTED]	Date	19 Mar 2020
Subject	Vibration Monitoring Report 8 Goulburn Base Hospital Redevelopment		Project No. 94054.07 Doc. No. 94054.07.R.008.Rev0

Installation and Monitoring

On 21 January 2020 Texcel Construction Vibration Monitors #7221, #7153 were relocated to the positions shown in the attached Monitoring Location Plan, before the start of augered piling. Both monitors were coupled to the ground with a surcharge, close to and at ground level of the adjacent building, which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works. On 26 February 2020, Monitor #7221 was replaced with Omnidot Vibration Monitor "Vujaca".

With reference to the CNVMP (the Monitoring Plan), an "Allowed Vibration Limit" of 25 mm/s vector sum peak particle velocity (VSPPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Value (VDV) of 0.20 m/s^{1.75} for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon - Sat, 6 am - 6 pm, with SMS (text message) alarms to be sent automatically to Eugene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 7 mm/s VSPPV, as a contingency for impulsive events).

The eVDV shown in the attached graphs is a calculated estimate of VDV from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities, wavelength durations and amplitudes (as detailed in NSW EPA Assessing Vibration: A Technical Guideline, February 2006). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring, and these criteria are indicative only, therefore consideration of continuous and impulsive vibrations is included (as recommended), see attached graphs. The table of acceptable daily Dose Values, Table 2.4, includes a "Preferred Value", being half of the "Maximum Value".

Outcome this period: 2 March to 9 March 2020

Location	Monitor	Exceedances		Time of maximum exceedance
		No.	Max (VSPPV)	
Monitoring Location A	Vujaca	0	n/a	n/a
Monitoring Location B	7153	0	n/a	n/a



Senior Geophysicist

Reviewed by



Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Limitations

Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yuncken Pty Ltd. The report is provided for the exclusive use of Hansen Yuncken Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time. Vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.


The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.

As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yuncken Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, re-installation and/or repair is required.

This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.

**Monitor
7153**


**Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location B - NE-cnr of pathology-mortuary building)**



**Monitor
7153**


Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)






**Monitor
VUJACA**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason they must be regarded as interpretive rather than factual documents limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Reference and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days or perhaps weeks for low permeability soils. Piezometers sealed in a particular stratum may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel based on the information obtained from field and laboratory testing and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal the information and interpretation may not be relevant if the design proposal is changed. If this happens DP will be pleased to revise the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects and recommendations or suggestions for design and construction. However DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities or
- The actions of contractors responding to commercial pressures.

If these occur DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.

Memorandum

To	[REDACTED]	Hansen Yuncken Pty Ltd	[REDACTED]
From	[REDACTED]	Date	19 Mar 2020
Subject	Vibration Monitoring Report 9 Goulburn Base Hospital Redevelopment		Project No. 94054.07 Doc. No. 94054.07.R.009.Rev0

Installation and Monitoring

On 21 January 2020 Texcel Construction Vibration Monitors #7221, #7153 were relocated to the positions shown in the attached Monitoring Location Plan, before the start of augered piling. Both monitors were coupled to the ground with a surcharge, close to and at ground level of the adjacent building, which includes Pathology (upper floor) and the Mortuary (lower floor). The monitors were installed to manage vibrations generated during piling works. On 26 February 2020, Monitor #7221 was replaced with Omnidot Vibration Monitor "Vujaca".

With reference to the CNVMP (the Monitoring Plan), an "Allowed Vibration Limit" of 25 mm/s vector sum peak particle velocity (VSPPV) was assigned by DP based on the potential for damage to the adjacent structures and a Vibration Dose Value (VDV) of 0.20 m/s^{1.75} for comfort of the occupants (whole body vibration). The monitors were configured for continuous monitoring Mon - Sat, 6 am - 6 pm, with SMS (text message) alarms to be sent automatically to Eugene Godfrey and DP in the event of vibration exceedances (vibration levels exceeding 7 mm/s VSPPV, as a contingency for impulsive events).

The eVDV shown in the attached graphs is a calculated estimate of VDV from velocity data rather than acquired acceleration data. The Dose Rate and Maximum Values refer to accumulated vibration activity per day during daytime hours and includes summations of RMS velocities, wavelength durations and amplitudes (as detailed in NSW EPA Assessing Vibration: A Technical Guideline, February 2006). "Critical Areas" includes hospital operating theatres and precision laboratories where sensitive operations are occurring, and these criteria are indicative only, therefore consideration of continuous and impulsive vibrations is included (as recommended), see attached graphs. The table of acceptable daily Dose Values, Table 2.4, includes a "Preferred Value", being half of the "Maximum Value".

Outcome this period: 9 March to 16 March 2020

Location	Monitor	Exceedances		Time of maximum exceedance
		No.	Max (VSPPV)	
Monitoring Location A	Vujaca	0	n/a	n/a
Monitoring Location B	7153	2*	28.7	12-Mar, 2:35 pm

*Isolated impulsive events, likely direct bumps to sensor.



Senior Geophysicist

Reviewed by



Principal

Attachments: Graphs of Vibration Levels, Monitor Location Plan, About This Report

Limitations


Douglas Partners Pty Ltd (DP) has prepared this report for Hansen Yuncken Pty Ltd. The report is provided for the exclusive use of Hansen Yuncken Pty Ltd for this project only and for the purpose(s) described in the report. It should not be used for other projects or by a third party. In preparing this report DP has necessarily relied upon information provided by the client and/or their agents.

DP's advice may be based on observations, measurements, tests, or derived interpretations. The accuracy of the advice provided by DP in this report may be affected by unobserved features and variations in ground conditions and conditions affecting vibration across the site, between and beyond the testing locations or by variations with time. Vibration monitoring and advice may also be limited by budget constraints imposed by others or by site accessibility.

The results provided in the report are indicative of the vibration levels at the sensor location(s) only and only during the specified period of monitoring. Vibration levels in other locations may therefore differ from those reported herein.


As neither estimations of safe operating distances for vibrations (if provided) nor the presence of an unattended vibration monitor can prevent exceedances, the real-time management of vibration remains the responsibility of Hansen Yuncken Pty Ltd and its plant operators. Interference with (e.g. movement or damage to) the monitoring equipment may influence readings and the Client is responsible for advising DP immediately to assess whether readings are affected, re-installation and/or repair is required.

This report must be read in conjunction with all of the attached notes and should be kept in its entirety without separation of individual pages or sections. DP cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.




**Monitor
7153**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - NE-cnr of pathology-mortuary building)




**Monitor
VUJACA**


**Vibration Levels - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)**



**Monitor
VUJACA**

Vibration Dose Values - Goulburn Base Hospital Redevelopment
(Monitoring Location A - SE-cnr of pathology-mortuary building)





About this Report

Douglas Partners



Introduction

These notes have been provided to amplify DP's report in regard to classification methods, field procedures and the comments section. Not all are necessarily relevant to all reports.

DP's reports are based on information gained from limited subsurface excavations and sampling supplemented by knowledge of local geology and experience. For this reason they must be regarded as interpretive rather than factual documents limited to some extent by the scope of information on which they rely.

Copyright

This report is the property of Douglas Partners Pty Ltd. The report may only be used for the purpose for which it was commissioned and in accordance with the Conditions of Engagement for the commission supplied at the time of proposal. Unauthorised use of this report in any form whatsoever is prohibited.

Reference and Test Pit Log

The borehole and test pit logs presented in this report are an engineering and/or geological interpretation of the subsurface conditions and their reliability will depend to some extent on frequency of sampling and the method of drilling or excavation. Ideally, continuous undisturbed sampling or core drilling will provide the most reliable assessment but this is not always practicable or possible to justify on economic grounds. In any case the boreholes and test pits represent only a very small sample of the total subsurface profile.

Interpretation of the information and its application to design and construction should therefore take into account the spacing of boreholes or pits, the frequency of sampling and the possibility of other than straight line variations between the test locations.

Groundwater

Where groundwater levels are measured in boreholes there are several potential problems namely:

- In low permeability soils groundwater may enter the hole very slowly or perhaps not at all during the time the hole is left open.

- A localised perched water table may lead to an erroneous indication of the true water table.
- Water table levels will vary from time to time with seasons or recent weather changes. They may not be the same at the time of construction as are indicated in the report and
- The use of water or mud as a drilling fluid will mask any groundwater inflow. Water has to be blown out of the hole and drilling mud must first be washed out of the hole if water easements are to be made.

More reliable easements can be made by installing standpipes which are read at intervals over several days or perhaps weeks for low permeability soils. Piezometers sealed in a particular stratum may be advisable in low permeability soils or where there may be interference from a perched water table.

Remarks

The report has been prepared by qualified personnel based on the information obtained from field and laboratory testing and has been undertaken to current engineering standards of interpretation and analysis. Where the report has been prepared for a specific design proposal the information and interpretation may not be relevant if the design proposal is changed. If this happens DP will be pleased to refile the report and the sufficiency of the investigation or not.

Every care is taken with the report as it relates to interpretation of subsurface conditions, discussion of geotechnical and environmental aspects and recommendations or suggestions for design and construction. However DP cannot always anticipate or assume responsibility for:

- Unexpected variations in ground conditions. The potential for this will depend partly on borehole or pit spacing and sampling frequency.
- Changes in policy or interpretations of policy by statutory authorities or
- The actions of contractors responding to commercial pressures.

If these occur DP will be pleased to assist with investigations or advice to resolve the matter.

About this Report

Site Information

In the event that conditions encountered on site during construction appear to vary from those which were expected from the information contained in the report, DP requests that it be immediately notified. Most problems are which are more readily resolved when conditions are exposed rather than at some later stage, well after the event.

Information for Contract Administrator

Where information obtained from this report is provided for tendering purposes, it is recommended that all information, including the written report and discussion, be made available. In circumstances where the discussion or comments section is not relevant to the contractual situation, it may be appropriate to prepare a specially edited document. DP would be pleased to assist in this regard and/or to make additional report copies available for contract purposes at a nominal charge.

Site Inspection

The company will always be pleased to provide engineering inspection services for geotechnical and environmental aspects of work to which this report is related. This could range from a site visit to confirm that conditions exposed are as expected, to full time engineering presence on site.